

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 631700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T27-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5277-78 and Pg. 5285-86)

(Pgs. 5277-78)

Set a W.Oak post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. S C ½ S. on N. face, from which

A B.Oak 10" dia., bears N.42°30'W., 110 lks. mkd. ¼ S BT.

A W.Oak 12" dia., bears N.73°E., 6 lks. mkd. S C ¼ S BT.

(Pgs. 5285-86)

Find the ¼ sec. cor. marked as reported by Examiner, and the W.Oak witness tree to bear N.53°E., 60 lks. dist., instead of N.73°E., 6 lks. dist. as reported in original notes. I erase redundant markings on the post to conform with original notes

Survey by Gene E. Johnson - March 15, 1955 - C.S. 42/194-2

Location determined from O.B.T.:

12" Oak, now 14", N.73°E., 6.0 lks., very rotten, scribe visible.

At corner point, Set 3/4" Iron rod, from which new BTs:

14" Oak bears N.82°00'W., 90.0 ft. scribed ¼ S36 BT RE3561

12" Oak bears N.11°15'E., 67.0 ft. scribed ¼ S36 BT RE3561

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - March 1961 - C.S. File 49/12-18

Found - Both BTs as recorded by Johnson, but do not find 3/4" I.R. set at corner.

Orig. 10" now 18" down B.Oak, N.42½°W., 72.6 ft., previously opened, shows good scribing "¼". Also find stump section in place.

Orig. NE. BT not found. Recorded as found by Johnson.

B.Oak, N.74°W., 102.0 ft., Johnson BT. (rec. N.82°W., 90.0 ft.)

B.Oak, N.10°E., 70.5 ft., Johnson BT. (rec. N.11¼°E., 67.0 ft.)

Set Brass cap at cor. mkd: County Surveyors Office
South ¼ S36 T27SR8W
1961

New BTs- 17" R.Fir bears N.6½°E., 33.9 ft. "S¼ S36 CS BT."

18" R.Fir bears N.80°W., 39.6 ft. "¼ S36 CS BT."

The North ¼ cor. sec. 1, T28-8, bears N.86°E., 594.9 ft., (Record, East 594.0 ft.)

continued next page

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 631700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T27-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tony Hostetter - For: Seneca Jones Timber Co. - Aug. 2002 - M140-72

Found - 1961 brass cap
24" Fir, face evident, BT tag, bears N.6½°E., 33.9 ft.
Rotten Fir windfall, BT tag, bears N.80°W., 89.6 ft.
New BTs- 18" Cedar, scribed "S36 ¼ BT" bears S.76°E., 7.7 ft. to spike.
20" Fir, scribed "S36 ¼ BT" bears S.88°W., 35.8 ft. to spike.

AMENDED CORNER ON TOWNSHIP LINE (NOT MONUMENTED) BEARS N.0°13'41"E., 78.91 FT.