

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 943170

PRIMARY CORNER DESCRIPTION Cor. No. 17 HES 143

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12021-2)

-----  
Cor. No. 17, identical with Cor. H/2 of listing survey No. 6-590, Tract 3, a fir tree, 24" dia., mkd. & witnessed as described by the listing surveyor. I mark tree 17 HES 143 on E face, with a blaze on the N & SW faces, for Cor. 17; from which

A hemlock, 8" dia., bears S.39°30'W., 26 lks.

A fir, 14" dia., bears N.41°30'W., 20 lks.

both trees blazed and scribed 17 HES 143 BT.

Pits & mound impracticable at this and all other cors.

-----  
Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage & V. Perron - 12/16/1969 - C.S. File 54/82-98

-----  
Found - Stump of Orig. 24", now 30" Fir Corner Tree, open & find scribe & reverse on East face

Both Orig. BTs destroy by roadway

Stump of Corner Tree badly decayed, we remove enough wood from South side to set in center a 1" IP &

Brass Cap Mkd: County Surveyors T29S R1E

Office, 1969 Cor.#17< HES 143

New BTs- 13" W.Fir S.36½°W., 99.0 ft. mkd: "17 HES 143 CS BT".

14" W.Fir N.5°W. 145.6 ft. mkd: "17 HES 143 CS BT".

Corner lies on E. edge of road

New BTs. on W. Side of Road.

-----  
Fd. BC & 2 BTs by Farr, USFS - July 1975 - M56-26