

TOWNSHIP 29 RANGE 01 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 14 Page 6083)

Set a porphyry stone 18x10x8", 12" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which

A fir, 6" dia., bears N.13°E., 17 lks., mkd: ¼ S28 BT.

A fir, 5" dia., bears S.7°W., 62 lks., mkd: ¼ S29 BT.
N.0°3'W. 0.15 chs. bet. secs. 28 & 29

The cor. which I established in my orig. survey under contract No. 757 as the ¼ sec. cor. bet. secs. 28 & 29 bears E 22 lks. I destroy the cor. & marks on BTs. (There is a record of Mensch's orig. survey on the internet)

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - April 17, 1969 - C.S. File 54/82-17

Reported as not found.

Found location poster for ¼ cor.

2 small firs for BTs gone.

Trees in the area now 38" even these trees probably too small.

Victor M. McLind - For: Umpqua Nat'l Forest - Oct. 6, 1971 - M42-39

Set - 2" Iron pipe with a 3" bronze disc. stamped:

T29S R1W
¼ S 29|S 28
RLS 934
1971

from which bears:

A 16" W.Fir scribed "¼ S29 BT" N.76¼°W., 42.1 ft.

A 16" W.Fir scribed "¼ S28 BT" N.36¼°E., 41.1 ft.

Note - No evidence of orig. corner found, corner reestablished by proportionate measurement from sec. corners.

Wayne Rogers - For: US Forest Service - Dec. 1978 - M70-44A&B

Found - 1971 brass cap per M42-39

20" Fir stump, N.76°W., 42.1 ft.

20" Fir stump (rec. N.36°E.) N.72°E., 41.1 ft.

New BTs- 6" Fir S.49°E., 18.56 ft.

6" Fir S.45°W., 16.77 ft.