

TOWNSHIP 29 RANGE 01 POINT IDENTIFIER # 700237

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30 only, T29-1E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Contract #797, dated April 19, 1910 - (DCSO records Vol. 15 Page(s) 6135)

Set a conglomerate stone 15x8x8 ins., 10" in the ground for cor. of secs. 19 and 30, marked with 4 notches on N. and 2 notches on S. edge, from which
A Fir 9" dia., bears N.83°E., 66 lks. dist. mkd. T29S R1E S19 BT.
A Fir 16" dia., bears S.64°E., 20 lks. dist. mkd. T29S R1E S30 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 16, 1969 - C.S. File 54/82-60

Found - Corner stone broken up in ground mkd. with "+" on top.
Orig. 9" now 11" Fir, N.83°E., 43.6 ft., down. We opened and found scribe and reverse.
Orig. 16" now 20" Fir S.64°E., 13.2 ft. Alive. Shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S
R1W | S 19 R1E
S 30
1969

New BT - 7" W.Fir N.42°E., 26.1 ft. mkd. T29S R1E S19 CS BT. Good blazed line from South. This cor. lies on moderate SE. slope in old growth Fir timber.