

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6272-73)

Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for 1/4 sec. cor., with brass cap marked $\frac{1}{4}$ $\frac{S28}{S33}$
1917

from which

A Fir 28" dia., bears N.37°30'E., 69 lks. dist. mkd. $\frac{1}{4}$ S28 BT.

A Fir 24" dia., bears S.64°W., 19 lks. dist. mkd. $\frac{1}{4}$ S33 BT.

Douglas Co. Surveyors Office - Clell Goodwin; Vic Cangie, L. Ladig, crew - Oct. 1, 1975 - C.S. File 57/36-14

Found - 1917 GLO brass cap, properly marked.
Orig. 24" Fir now 36", alive and well healed, bears S.64°W., 12.5 ft.
Orig. 28" Fir now 28" rotted stump with no visible scribe marks bears N.37½°E., 45.5 ft.
New BT - 7" Fir scribed " $\frac{1}{4}$ S28 CS BT" in a double blaze bears N.18½°E., 30.3 ft.