

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6262)

 Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 27, 28, 33 and 34, with brass cap mkd:

T 29 S R 2 W	
S28	S27
S33	S34
1917	

from which

- A Fir 30" dia., bears N.85°E., 12 lks. dist. mkd. T29S R2W S27 BT.
- A Fir 24" dia., bears S.19°E., 42 lks. dist., mkd. T29S R2W S34 BT.
- A Balsam Fir 10" dia., bears S.46°W., 60 lks. dist., mkd. T29S R2W S33 BT.
- A Balsam Fir 15" dia., bears N.42°W., 57 lks. dist. mkd. T29S R2W S28 BT.

Douglas Co. Surveyors Office - Clell Goodwin; Vic Cangie - Sept. 22, 1975 - C.S. File 57/36-9

-
- Found - 1917 GLO brass cap, properly mkd., on 1" x 30" I.P. Orig. 24" now 30" Fir, bears S.19°E., 29.9 ft. (call S.19°E., 27.7 ft.) alive and well healed.
 Orig. 10" now 17" Fir bears S.46°W., 39.6 ft. alive and healed.
 Orig. 30" Fir now rotted stump with no visible scribe, bears N.85°E., 7.9 ft.
 No recognizable remains of original NW. BT.
- New BT - 12" Fir scribe "T29S R2W S28 CS BT" in a double blaze bears N.43½°W., 9.2 ft.
 14" Fir scribed "T29S R2W S27 CS BT" in a double blaze bears N.57°E., 22.9 ft.