

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only, East

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6211-12)

Set an iron post 3 ft. long, 2" dia., 24" in the ground for cor. of secs. 1 and 12 with brass cap marked:

T29S	
S1	
S12	
R2W	
1917	

from which

A Pine 12" dia., bears S.25°30'W., 41 lks. dist. mkd. T29S R2W S12 BT.

A Fir 12" dia., bears N.35°W., 21 lks. dist. mkd. T29S R2W S1 BT.

Douglas Co. Surveyor Office - Dennis Gaylord, U.S.F.S. (Deputized by the County) Wit: Roland Simshauser - April 20, 1978 - C.S. File 59/46-41

Found - 1917 GLO brass cap, properly stamped, on a 1½" I.P., 4" above ground.

24" Fir stump bears N.35°W., 13.86 ft., open and find scribing and reverse. Placed a county BT sign on the stump.

BT location for SW. BT falls in Road #2848.

Corner stone for sec. cor. for 6 & 7, T29-1, bears N.1°15'E., 8.1 ft. (Rec. North 7.92 ft.)

No new monument set.

New Accessories:

A 5/8" Iron rod with a 1" alum. cap mkd. R.M. S34°E 12.6', bears N.34°W., 12.6 ft.

A 5/8" Iron rod with a 1" alum. cap mkd. R.M. N.51½°E 9.8', bears S.51°30'W., 9.8 ft.

Corner lies 20 ft. North of F.S. Road #2846 in a clearcut.