

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6336)

-----  
Set Laurel post for the ¼ sec. cor., from which  
A Laurel 10" dia., bears N.62°E., 16 lks. dist.  
A Fir 24" dia., bears N.30°W., 10 lks. dist.

Survey by John H. Markham, Jr. - Wit: Geo. Vaughn - Aug. 17 & 25, 1950 - C.S. File 40/272-4

-----  
Determined by O.B.T.:  
A Fir 33" dia., bears N.30°W., 6.5 ft. Scribe legible. I remark ¼ S BT.  
At corner point, Set 3/4"x30" IP, 15" in ground, from which  
A Laurel 12" dia., bears S.60°W., 43.6 ft. mkd. ¼ S S22 2880 BT.  
A B.Oak 14" dia., bears S.77°E., 38.0 ft. mkd. ¼ S S23 2880 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Nov. 1962 - C.S. File 52/126-83

-----  
Found - 1" I.Pipe at corner.  
SW. BT as recorded by Markham is OK.  
SE. BT, now dead.  
New BT - 15" Pine bears N.43°E., 59.4 ft. scribed ¼ S23 CS BT  
Corner is 30 ft. South of top E-W ridge.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2033, surveyed Sept. 2002/June 2003 (DCSO rec. Vol. 55 pg(s) 21327-8)

-----  
The ¼ sec. cor. of secs. 22 & 23, perpetuated by Markham, in 1950, & by the Douglas Co Surveyors Office, in 1962, monumented with an iron pipe, 1½" dia. firmly set, projecting 18" above ground, from which the remains of an original BT  
A roothole bears N.30°W., 6.6 ft., with fallen, decayed fir trunk 30" dia lying alongside with no marks visible and remains of bearing trees mkd. by Markham  
An oak snag, size indeterminate, bears S.79¼°E., 38.5 ft., with no marks visible.  
A madrone, 19" dia., bears S.61½°W., 43.6 ft., with no marks visible.  
and remains of a BT mkd. by the Douglas Co Surveyors Office  
A decayed pine stump, 27" dia., bears N.39¼°E., 59.0 ft. with fallen, decayed trunk lying alongside, with healed blaze.  
continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the cor. point  
Set a stainless steel post, 28" long, 2½" dia., 25" in the ground, with brass cap mkd. T29S R3W

¼  
S 22 | S 23  
2003

from which new bearing trees

A fir, 8" dia., bears N.23¼°E., 13.1 ft., mkd. ¼ S23 BT.

A cedar, 12" dia., bears S.87¾°W., 20.2 ft., mkd. ¼ S22 BT

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

Deposit a magnet in a white plastic case at the base of and bury the iron pipe inside the stainless steel post.