

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6337-38)

-----  
 Set Dogwood post for the cor. to secs. 2, 3, 10 and 11, from which

- A Fir 40" dia., bears N.89°E., 37 lks. dist.
- A Laurel 12" dia., bears S.20°E., 56 lks. dist.
- A Laurel 12" dia., bears S.80°W., 98 lks. dist.
- A Fir 30" dia., bears N.30°W., 81 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13803)

-----  
 Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T	29	S	R	3	W
	S	3	S	2	
	S	10	S	11	
				1964	

from which

- A Fir 10" dia., bears N.28½°E., 168 ks. dist., mkd. T29S R3W S2 BT.
- A Fir 10" dia., bears S.40°E., 46 lks. dist., mkd. T29S R3W S11 BT.
- A Fir 7" dia., bears S.51¼°W., 8 lks. dist., mkd. T29S R3W S10 BT.
- A Fir 10" dia., bears N.47 3/4°W., 103 lks. dist., mkd. T29S R3W S3 BT.

Douglas Co. Surveyors Office - Stephen J. Flause; Bill Stewart, crew - Sept. 29, 1980 - C.S. File 61/11-24

-----  
 Found - 1964 BLM brass cap on a 2" iron pipe, protruding 7" from ground, firmly set and properly marked.

- A thorough search of the area employing original line calls yields no evidence of original trees.
- 10" now 15" DBH, D.Fir bears N.28½°E., 110.9 ft. (per BLM record) Tree has healed single blaze with no scribing visible.
  - 10" now 16" DBH D.Fir bears S.50°E., 30.0 ft. (Rec.S.40°E. 30.4 ft.) Tree has healed single blaze, no scribing visible.
  - 7" now a 9" DBH D.Fir bears S.51¼°W., 6.0 ft. (Rec. S.51¼°W., 5.3 ft.) Tree has healed single blaze, no scribing visible. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	Description

10" now a 12" DBH D.Fir bears N.47 3/4°W., 67.0 ft.  
(Rec. N.47 3/4°W., 68.0 ft.) Tree has healed  
single blaze, no scribing visible.  
We accept position of monument as there is no evidence that  
it has been disturbed. Discrepancies from record bearings  
and distances seem to indicate recording or measurement  
errors.  
New Accessory:  
A rough fence corner with fences running North and  
East, lies approx. 20 ft. North of the brass cap.  
All trees re-tagged with DCSO bearing tree tags.

---

Fd. OK, May 1992 by Wm. Ruppert - Land Partition, 1992-0038

---

Fd. OK by D. Edwards, Oct. 1998 - M130-67  
Fd. OK by D. Edwards, June 2007 - M153-49

---

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor  
and Robert H Browning, Survey Tech, Under Group No. 2154,  
Surveyed April/May 2007 - DCSO records Vol. 57 Page(s) 22570  
-----  
The cor. of secs. 2, 3, 10, and 11, monumented with an iron  
post, 2½" dia., firmly set, projecting 8" above the ground,  
with brass cap (properly) mkd.  
from which the remains of BTs mkd. by Beck in 1964-65  
A fir, 22" dia., bears N.28½°E., 110.9 ft., with a healed  
blaze.  
A fir, 23" dia., bears S.49¼°E., 30.4 ft., with a healed  
blaze. (Record, S.40°E.)  
A sawed fir stump, 12" dia., bears S.51¼°W., 5.3 ft., with  
no marks visible.  
A fir, 15" dia., bears N.47¾°W., 68.0 ft., with a healed  
blaze.  
The cor. of woven wire fences extending N. and E. bears  
N.7°E., 19.0 ft.  
(NAD 1983 (CORS 96))  
Latitude: 43°04'13.49"N Longitude: 123°02'26.06"W

---

BLM resurvey by George M. Winter, Cadastral Surveyor under  
Group No. 2654, surveyed Oct./Nov. 2012 - (DCSO records Vol.  
58 Page(s) 23026-7)  
-----  
The cor. of secs. 2, 3, 10, and 11, monumented with an iron  
post, 2½" dia., firmly set, projecting 7" above ground, with  
brass cap (properly) mkd.  
from which the remains of BTs mkd. by Beck in 1964-65  
A fir, 25" dia., bears N.28½°E., 110.9 ft., with a healed  
blaze. continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A fir, 25" dia., bears S.49½°E., 30.4 ft., with a healed blaze.

A sawed, decayed fir stump, 13" dia., bears S.51¼°W., 5.3 ft., with no marks visible.

A fir, 16" dia., bears N.47¾°W., 66.8 ft., with a healed blaze. (Record, 68.0 ft.)

and a new bearing tree

A fir, 4" dia., bears S.60°W., 59.7 ft., mkd. X BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Corner is located 6 ft. W. and 18 ft. S. of fences extending N. and E.

NAD 1984 (2011)

Latitude: 43°04'13.49"N.      Longitude: 123°02'26.06"W.