

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1 (NE Tsp. Cor.)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6324)

Established true corner to townships 28 and 29 S., Ranges 2 and 3 W. at point of intersection. Set a Maple post for said corner, from which

- A Fir 10" dia., bears N.70°E., 8 lks.
- A Fir 8" dia., bears S.20°E., 25 lks.
- A Fir 4" dia., bears S.50°W., 7 lks.
- A Fir 10" dia., bears N.10°W., 10 lks.

GLO resurvey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5548)

Cor. of T.29S., Rs. 2 and 3 W., which is a stake marked and witnessed as described by the Surveyor General. I destroy markings on this cor. referring to T.28 S.

GLO Resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6232)

Intersect the cor. of Tps. 29S., Rs. 2 and 3 W., which is the remains of a decayed post, nearly obliterated, witnessed as described by the surveyor general. I perpetuate this cor., as follows: at the exact cor. point

Set an iron post, 3 ft. long, 3" dia., 24" in the ground for cor. to Tps. 29 S., Rs. 2 and 3 W., with brass cap marked:

T28S R3W
 S36
 S1 S6
 R3W R2W
 T29S
 1917

from which

- A Fir 8" dia., bears S.20°E., 25 lks. dist., marked T29S R2W S6 BT (Old BT)
- A Fir 16" dia., bears S.42°45'W., 39 lks. dist. marked T29S R3W S1 BT. (New BT)

BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15842-43)

(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1 (NE Tsp. Cor.)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The cor. of Tps. 29 S., Rs. 2 and 3 W., established by Byars in 1881, changed to a corner of minimum control by Gibb, in 1910, and rehabilitated by Strickler in 1917, monumented with an iron post, 3" dia., firmly set, projecting 12" above ground, and marked as shown by Strickler

from which the remains of the original bearing tree:

A root hole bears S.20°E., 25 lks. dist., with a down Fir alongside, 18" dia., with healed blaze. This tree was remarked by Strickler.

and the remains of a bearing tree by Strickler:

A root hole bears S.42½°W., 39 lks. dist., with a down Fir alongside, 18" dia., with healed blaze.

and new bearing trees:

A Fir 17" dia., bears S.66¼°E., 44 lks. dist., mkd. T29S R2W S6 BT.

A Fir 23" dia., bears S.27 3/4°W., 58 lks. dist. mkd. T29S R3W S1 BT.