

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6379)</p> <p>-----</p> <p>Set ¼ sec. post at average dist., from which A B.Oak 18" dia., bears S.63°W., 66 lks. dist. A Laurel 6" dia., bears N.23°W., 32 lks. dist.</p>
<p>G.A. Barnhart, Surveyor - Wit: Weber and Stubblefield - Dec. 1946 (added 8/6/2024) - C.S. File 40/19(D)</p> <p>-----</p> <p>From the NW corner of section 32 I ran N.89°30'E., the given distance to the ¼ corner (2659.8 ft) and to the NE corner of Section 32 (5319.6 ft) The ¼ corner came in an old burn, could not find any signs of the bearing trees. Could not find any of the bearing trees at the section corner. Did find a few line blazes between the ¼ corner and the section corner.</p>
<p>Jack L. Sheppard, LS #180 - For: Umpqua Plywood - Jan/Feb. 1955 - C.S. File 41/337 and M 3-68</p> <p>-----</p> <p>Set 1" Iron pipe, by proportion. Scribed two trees: 8" Cedar S.13°E., 20.8 ft. scribed ¼ S32 LS 180 BT. 24" Fir N.67½°E., 26.0 ft. scribed ¼ S29 LS 180 BT.</p>
<p>Fd. Ok by D. Edwards, March 2002 - M139-75</p>
<p>David Edwards - For: Roseburg Resources Co - 4/2018 - M174-36</p> <p>-----</p> <p>Found - 1" dia., iron pipe per M3-68 A 35" dia., fir bears N.67½°E., 26.0 ft. A 23" dia., cedar bears S.13°E., 20.8ft. Both with healed blaze Set - A 6 ft steel post S.16°W., 2 ft.</p>
<p> </p>