

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6377)

Set 1/4 sec. post at average dist., from which
A B.Oak 10" dia., bears S.38°W., 49 lks. dist.
A B.Oak 12" dia., bears N.10°E., 78 lks. dist.

Survey by John H. Markham, Jr. - For: Hult Lumber Co. - April/June 1964 - C.S. File 51/292 and M 28-25

Set 1" x 36" Iron pipe at mid-point.
New BTs -9" W.Oak bears N.4°30'W., 149.7 ft. mkd. 1/4 S16 BT
14" W.Oak bears N.20°W., 175.8 ft. mkd. 1/4 S XX BT
A 3-way fence corner bears N.34°30'W., 213.2 ft.
Corner lies in a level cow pasture.

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #'s 255; 701; 938 - Surveyed July/Oct 1977 (DCSO records Vol. 39 Page(s) 15883)

Point for the 1/4 sec. cor. of secs. 16 and 21, at proportionate distance based on record ties of the Hathorn survey of the claim lines; there is no remaining evidence of the original corner.

Set an iron post 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:
T 29 S R 4 W
1/4 S 16
S 21
1969

from which bearing trees mkd. by Markham in 1964:
An Oak 11" dia., bears N.19 1/2°E., 259 lks. dist., with healed double blaze.
An Oak 15" dia., bears N.3°E., 268 lks. dist., with helaed blaze.
Markham's bearing trees were utilized because no other trees were available within limits.

From this point, a local corner, established by Markham in 1964, bears N.79°40'W., 1.07 chs. dist. monumented with an iron pipe 1" dia., firmly set flush with surface of the ground.
Corner is located in an open field.

Fd. OK, Aug. 1993 by B. Shaner - RM 3-79