

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6359)</p> <p>-----</p> <p>Set ¼ sec. post, from which A B.Oak 10" dia., bears S.33°W., 82 lks. dist. A B.Oak 12" dia., bears N.43°E., 64 lks. dist.</p>
<p>GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 15 Page(s) 6404) and (Vol. 17 Page 7068)</p> <p>-----</p> <p>A post in place, probably set by Deputy Byars in 1872; also the two bearing trees are standing. I replace the post, being partly decayed, by a Yew post, 3 ft. long, 3" sq., 24" in the ground, mkd. ¼S on N. face, from which A Maple 8" dia., bears N.80°E., 19 lks. dist. mkd. ¼ S BT. A Yew 8" dia., bears N.39°E., 11 lks. dist. mkd. ¼S BT. (The bearing trees of this corner are given as between secs. 4 and 33 in the field notes of original survey, furnished me.)</p>
<p>Douglas County Surveyors Office - James W. Byron, Surveyor (Symbol for "not found" on visual map, but no CS source or date, could be found.)</p> <p>-----</p> <p>Corner searched for, not found.</p>
<p>Ron Quimby - For: Roseburg Forest Products - March 1996 - M 123-58</p> <p>-----</p> <p>Found - 2½" steel pipe with BLM brass cap from which a: 8" D.Fir, bears N.67½°W., 24.1', w/visible scribing. 7" Cedar, bears N.20½°W., 17.5' w/visible scribing.</p>
<p>BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20089-90)</p> <p>-----</p> <p>Beginning at the ¼ sec. cor. of sec. 34 only, at proportionate distance determined by the Irregular Boundary Method; there is no remaining evidence of the original corner. Set a stainless steel post, 28" long, 2½" diam., 24 in the ground, with brass cap mkd.</p> <p style="text-align: right;">continued next page</p>

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T29S R4W  
¼ S 34  
T30S R4W  
1994

from which

A fir, 8" diam., bears N.67½°W., 36½ lks., mkd. ¼ S34 BT.

A cedar, 7" diam., bears N.20½°W., 26½ lks., mkd. ¼ S34 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2777, surveyed June/July 2015/- (DCSO records Vol. 58 Page 23511)

-----  
The ¼ sec cor of sec 34 only, on the S bdy of T29S R4W monumented with a stainless steel post, 2½" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd. from which BTs mkd. by Seibold and Browning in 1993-95

A fir, 10" dia., bears N.67½°W., 24.1 ft., with a healed blaze.

A cedar, 13" dia., bears N.20½°W., 17.5 ft., with a healed blaze.

The closing cor. of secs. 3 and 4, on the N. bdy. of the Tp., bears N.88°54'54"W., 379.30 ft.