

PRIMARY CORNER DESCRIPTION WNW Cor. Whitted DLC #44

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original DLC survey by Burnett & Bowman under Contract date 1855. (D.L.C. Records Book, page(s) 548)</p> <p>-----</p> <p>Set a post marked from which; A Black Oak, 7" dia., bears S.88½°E., 20 lks.</p>
<p>Douglas Co. Surveyors Office - M.B. Germond, Co. Surveyor - Witnesses: Ed Weaver, Cleal Weaver, Hank Weaver, Joe Weaver, F.C. Frear, John Dicks, Harry Strong, & Chris Christesen - March/Sept. 1917 - FB 42 Pg 29 - "Old" Cor. Book PG 125</p> <p>-----</p> <p>I renew this corner from one old bearing tree. Old scribe marks plainly seen by all. New corner is ½"x36" Gal. Iron Pipe, from which: A Black Oak, 30" dia., bears S.24°E., 104.8 lks. A Black Oak, 18" dia., bears N.13°15'W., 30.0 lks.</p>
<p>Fd. Ok by Garrett - 2/1973 - M 47-63</p>
<p>Douglas County Surveyors Office - Randall Smith & Stephen Flause - Feb. 7, 1996 - C.S. 64/66-5</p> <p>-----</p> <p>Mon. Fd. - ½" I.D. iron pipe, protruding 10" above ground top of I.P. is bent. Brg's & dist's taken to plumb position of I.P. Bt's Fd. - 7" now 30" dia. 1½' high rotted oak stump, possible rotted blaze, no scribing found, bears S.88½°E., 13.2'. 18" now 24" dia. 1' high rotted oak stump no scribing or blazes visible, bears N.13¼°W., 19.8'. 30" now 31" dia. B.Oak with a fully healed single blaze, bears S.24°E., 69.2'.</p> <p>Mon. Set - Plumb positon of I.P. is referenced I.P. measured 31" long. 2 3/8" O.D. by 32" long iron pipe is set at referenced positon. BC/IP protrudes 3" above groud ½" I.D. I.P. is set along south edge of BC/IP. Protrudes 1" above ground.</p> <p>New BT's - 6" dia. D.Fir, double blazed and scribed "WNW DLC 44 CS BT", bears S.85 3/4°E., 22.7'. 9" dia. I.Cedar, double blazed and scribed "WNW DLC 44 CS BT", bears S.20½°E., 54.8'. 8" dia. D.Fir double, blazed and scribed "WNW DLC 44 CS BT", bears S.61°E., 6.5'.</p>
<p>Fd. Ok by Raymond Brown - 11/1998 - M129-29 Fd. OK by Raymond Brown - Mar. 2001 - M136-76</p>