

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 046010

PRIMARY CORNER DESCRIPTION NE Cor. Cornelison DLC # 46

Alias 047040 Description SSE Cor. Ireland DLC # 47  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original DLC survey by Burnett & Bowman under Contract date 1855. (D.L.C. Records Book, page(s) 551 & 553)

-----  
Set a post marked as per instructions, from which;  
A White Oak, 12" dia., bears N.75°E., 88 lks.  
No tree on claim in reasonable distance.

C. Baker - R. Asburry - E. DuBell - For: Guy Conley - 2/6/47  
- C.S. File 40/1

-----  
Point set from BT as per records.

Douglas Co. Surveyors Office - James W. Byron, Co. Surveyor  
-John M Powell & Crew - April 1969 - C. S. File 54/84 - M 37-44

-----  
Found - ½" I.P. N.1½°W., 5.07' from DLC #46, no record.  
Orig. 12" now 30" W. Oak, N.75°E., 58.2', opened,  
show scribe "B".  
Unrecorded 16" W. Oak, S.66½°E., 65.3', shows good  
scar.

Reset this corner from Orig. Bear. & dist. from BT.  
Set - Brass Cap at cor. mkd:

County Surveyor's T29S R5W  
Office, 1969  
NE Cor.

DLC | #46  
S 26

New BTs- 16" W. Oak, S.66½°E., 65.3' mkd: "NE DLC #46 CS BT"  
14" W. Oak, N.63½°E., 97.8' mkd: "NW DLC #46 CS BT"

Note - This corner lies on south slope N.77°W., 11.0' from  
a 3-way fence corner, see sketch in file.

FD OK, by W. Ruppert, 8/92 - M 112-55  
Fd. OK by Bentz, July 1995 - M124-5

DCSO-GIS Corner visitation - 1/9/2001 - Typed: 2/1/2011 -  
C.S. File 67/33-1

-----  
Monument - BC/IP  
Comment - OK