

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 040020

PRIMARY CORNER DESCRIPTION NW Cor. Clark DLC #40

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Bowman and Burnett, under Contract dated Sept. 1855

-----  
Right bank of South Umpqua River. Set post 4.50 chs. East of true corner in right edge of river, marked from which  
An Ash 4" dia., bears S.40°E., 26 lks. dist.

-----  
Arthur Boyer - Wit: A. Wecks and T. Shattenkirk - Feb. 1953  
-C.S. File 41/115

-----  
Set 1" x 1" x 18" Bolt, from which  
24" B.Oak bears S.85°W., 74.7 ft. mkd. C40 T29S R6W - 1581  
BT.  
Tree is on edge of field where slope starts to river and about 90 ft. South of phone line.

-----  
Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 8/31/2009 - C.S. File 67/28-35

-----  
Reported as not found.  
Found 2004 BT tag nailed to trunk, no record.  
No root hole evident. Herber Spangler property owner does not remember seeing any scribing, but indicated he felt that it had a blaze. No monuments found.  
Not enough evidence to reestablish 1953 DLC corner (M26-30)