

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6477)

Set post, cor. secs. 3, 4, 9 and 10, from which
A B.Oak 10" dia., bears S.81°E., 99 lks. dist.
A W.Oak 20" dia., bears N.42½°E., 114 lks. dist.
A W.Oak 24" dia., bears N.2½°W., 142 lks. dist.
A W.Oak 20" dia., bears S.45°W., 138 lks. dist.

Frank Cain (?) - For: Rice Bros. - May 27, 1915 - Field Book 37 Page 40

Found all 4 BTs standing. Correct bearings and distances are:
B.O. 10" S.81°E., 99 lks.
W.O. 20" N.39°E., 107 lks.
W.O. 24" N.1°W., 132 lks.
W.O. 20" S.35½°W., 127 lks.

G.G. Stewart, D.C.S. - Wit: Abner Rue, J.H. Adams, Dick Redding and H. Erskine - April 17-19, 1922 - Vol. 3 Pg. 118 (and "old" corner book, pg. 131

Found four original BTs. Set iron pipe for corner. Not all BTs checked for bearing but I put in corner from distances which checked. Marked
A 20" W.Oak S.37°W., 84.5 ft.
A 18" B.Oak S.81°E., 65.3 ft. O.B.T.
A 16" W.Oak N.42°E., 17.5 ft.
A 30" W.Oak, North, 93.7 ft. O.B.T.

Douglas Co. Surveyors Office - James Byron, Deputy - Ray Irving, John Fee, crew - June 1954 - C.S. File 46/45-1(J)

Found - ½" Iron post at corner.
Old 20" BT, S.37°W., 84.5 ft., down.
Old 18" B.Oak BT standing but rotted, S.81°E., 65.3 ft., no scribes visible.
Old 16" W.Oak BT, N.42°E., 17.5 ft., alive and standing, blazed and grown over.
Old 30" W.Oak BT, North 93.7 ft., alive and standing, blaze grown over.
All old BTs check for bearing and distances.
Blazed and scribed:
14" R.Fir S.70°E., 30.8 ft. S10 T29S R6W CS BT.
6" R.Fir S.75°W., 18.7 ft. S9 T29S R6W CS BT.

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Peter Peterson and Daniel Berry under Group #750, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14618-19)

The Sec. Cor. perpetuated by Stewart in 1922, further perpetuated by Byron in 1954, monumented with an iron pipe 1/2" dia., firmly set, protruding 5" above ground, with brass cap marked

D
from which the remaining original bearing trees

A root hole bears S.81°E., 99 lks. with a down and decayed B.Oak, size indeterminate, alongside, with no marks remaining.

A W.Oak 36" dia., bears N.1°W., 142 lks. with healed blaze. (Rec. bearing N.27°W.)
and a bearing tree marked by Stewart in 1922

A W.Oak 16" dia., bears N.40°E., 27 lks. with healed blaze.

and bearing trees marked by Byron in 1954

A Fir 18" dia., bears S.71°E., 46 lks. dist., with healed blaze.

A Fir 12" dia., bears S.74°W., 29 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 29 S R 6 W
S 4 | S 3
S 9 | S 10
1971

Deposit the iron pipe alongside the iron post.