

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6476)

Set 1/4 sec. post at average dist., from which
A W.Oak 20" dia., bears S.18°W., 70 lks. dist.
A B.Oak 20" dia., bears N.11°W., 21 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell, Dale McFarland, crew - April 1962 - C.S. 49/139-42

Found - Both original BTs. Orig. 20" B.Oak now 28" Oak snag, N.11°W., 13.9 ft. center rotted, shows old axe work.
Orig. 20" now 27" W.Oak S.18°W., 39.6 ft. We open and find good scribing.
Also find 1/4" I.P. at corner.
Corner bears N.35°W., 5 ft. from fence corner. fences running West and South.
New BTs -Rescribe O.B.T., now 27" W.Oak S.21°W., 46.5 ft. 1/4 S15 CS BT.
9" W.Oak bears N.19 1/2°W., 11.7 ft. scribed 1/4 S10 CS BT.

BLM resurvey by Peter Peterson and Daniel Berry under Group #750, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14616)

The 1/4 sec. cor., perpetuated by Byron in 1962, monumented with an iron pipe, 1/4" dia., firmly set, protruding 6" above ground, from which the only remaining original bearing tree
A W.Oak 27" dia., bears S.18°W., 70 lks. dist., with fragmentary scribe marks visible on opened blaze and scribe marks 1/4 S15 CS BT visible on partially healed blaze. (Remarked by Byron in 1962)
and a bearing tree marked by Byron in 1962
A W.Oak 10" dia., bears N.22°W., 16 lks. dist., with healed blaze.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
1/4 S 10
S 15
T 29 S R 6 W
1971
Deposit the iron pipe alongside the iron post.
Corner located on spur, slopes SW.