

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6469)

Set post, cor. of secs. 22, 23, 26 and 27, from which
A B.Oak 8" dia., bears S.57½°E., 28 lks. dist.
A Fir 12" dia., bears N.12°E., 28 lks. dist.
A Fir 10" dia., bears N.57°W., 31 lks. dist.
A Laurel 8" dia., bears S.69½°W., 32 lks. dist.

Survey by Jesse W. Cole - For: Rice Brothers - Feb/March 1924
Vol. 3 Pg. 183; F.B. 90 Pgs. 36-46; F.B. 52 Pgs. 48-55

I renewed this corner from the original bearing trees, three of which could be identified as they showed the scribe marks. The Oak BT was missing. I set a cedar post and marked new trees as follows:

A Fir 30" dia., S.45°30'E., 14.4 ft.
A Fir 30" dia., S.12°W., 10.4 ft.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: Geo. & Wm. Vaughn - Dec. 2-9, 1950 - C.S. File 40/294

Determined by O.B.T., a Fir 12" dia., bears N.12°E., 18.5 ft. scribe legible. I remark S 23 BT.

At corner point found scribed post, from which

A Fir 10" dia., bears N.57°W., 20.5 ft. mkd. S22 2880 BT.
A Fir 24" dia. bears S.16°W., 9.5 ft already mkd S27 CS BT
A Fir 28" dia., bears S.48°E., 14.0 ft already mkd. S26 BT

Cadastral survey by Hans W. Thielsen and C. Albert White under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug. 5, 1959 (DCSO records Vol. 30 Page(s) 12816)

The Sec. Cor. perpetuated with an iron pipe 1" dia., 6" above ground, firmly set. This cor. was established by Ford in 1854. The Douglas County records show that Arthur Boyer*, Deputy County Surveyor, remonumented the cor. with the iron pipe and marked new bearing trees, in 1941. Boyer states that the cor. was determined from original bearing trees marked by Ford. (*Note: It appears that it was J. Markham in 1950 not Boyer in 1941 that re-monumented the corner, per research 2/23/2011. JC DCSO)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. dia., 20 ins. in the ground, with brass cap mkd:

T 29 S R 6 W
S 22 | S 23
S 27 | S 26
1958

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which trees marked by Boyer in 1941:
A Fir 35" dia., bears S.46°E., 23½ lks. mkd. S BT.
A Fir 31" dia., bears S.16½°W., 16 lks. mkd. S27 CS BT.
A Fir 12" dia., bears N.57½°W., 30 lks. mkd. BT on partly open blaze.
and new bearing trees:
A Fir 15" dia., bears N.13¼°E., 29 lks mkd T29S R6W S23 BT
A Fir 35" dia., bears S.46°E., 23½ lks mkd T29S R6W S26 BT
A Fir 31" dia., bears S.16½°W., 16 lks mkd T29S R6W S27 BT
A Fir 12" dia., bears N.57½°W., 30 lks mkd T29S R6W S22 BT
Bury the iron pipe alongside the iron post.

Fd. Brass cap & 4 BTs by H. Johnstone, 4/1978 - RM3-12

DCS0-GIS Corner visitation - 8/18/2004 - Typed: 2/1/2011 - C.S. File 67/33-1

Monument - GLO/BLM 2.5" BC/IP
Comment - (needs) rehab

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - Feb. 23, 2011 - C.S. File 67/33-17

Found - 1959 BLM 3¼" dia., brass cap (properly mkd) on a 2½" dia., iron pipe firmly set protruding 1 ft. above ground. Iron pipe of unknown orig. fd and buried in 1959 renewal is not seen.
One tree at location of orig. NW BT (possibly OBT but described as a new BT by both Markham in 1950 and BLM in 1959). A fir 10" now a 20" DBH, D.Fir with a fully healed rescribing blaze; bears N.57°W., 20.5 ft. (as per orig. rec.) Because this tree is pistol butted and leaning we do not open to search for orig. scribing.
A fir 30" dia., now a 2½ ft. tall 32" dia., rotted fir stump with possible evidence of a bark blaze (no scribing seen) bears S.45½°E., 14.4 (as per rec) 1924
A fir 30" dia. now a 33" DBH D.Fir with a weathered bark blaze showing scribing "T29S R6W 7 BT", bears S.12°W., 10.4 ft. (as per rec.) 1924
NE BT, A fir 15" dia., now a fallen & very rotted approx. 18" dia., fir with an indistinct root depression near the record B & D of N.13¼°E., 19.1 ft. No marks are found. 1959
New BT - A 12" DBH D.Fir scribed "T29S R6W S23 CS" "BT" on a double blaze; bears N.40°E., 36.6 ft.
continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Monument is on steep forested Northwest slope.
Compass decl. 15¾°E.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24009-10)

The cor. of secs. 22, 23, 26, and 27, reported by Thielsen and White in 1958-59; perpetuated by Smith, in 2011; monumented with an iron post, 2½" dia., firmly set, projecting 14" above ground, with a brass cap (properly) mkd. from which the remains of the BTs reported by Thielsen & White

A decayed fir stump, 26" dia., bears S.46°E., 15.5 ft., with a healed blaze.

A fir, 34" dia., bears S.16½°W., 10.6 ft., with scribe marks T29S R6W BT visible on bark.

A fir, 21" dia., bears N.57½°W., 19.8 ft., with a healed blaze. (Original)

and a bearing tree mkd. by Smith

A fir, 12" dia., bears N.40½°E., 36.9 ft., with a healed blaze.

and a new bearing tree

A fir, 6" dia., bears S.69°E., 32.0 ft., mkd. T29S R6W S26 BT.