

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6471)

Set ¼ sec. post, from which
 A W.Oak 12" dia., bears S.53½°E., 81 lks. dist.
 A B.Oak 6" dia., bears N.59°W., 49 lks. dist.

F.C. Frear, Deputy Co. Surveyor - For: O.W. Ronk, Fred Smith; L.N. Sargisson - May 1919 - F.B. 46 Pgs. 47-57; Vol. 3 Pg. 62-64 (and "old" corner book, pg. 130)

Renewed from old BTs which I remarked and set a 3/4" x 36" galv. iron pipe for corner from which
 An 8" Fir bears S.69°E., 10 lks., C.S.B.T.
 A 5" W.Oak bears S.57½°W., 7 lks., C.S.B.T.

Douglas Co. Surveyors Office - James Byron, Deputy- Dale McFarland; John Powell, - April/May 1962 - C.S. 49/139-44

Found - 3/4" I.P. at cor. and 8" now 16" R.Fir S.69°E., 6.6 ft. shows good scar. This BT now four-way fence corner.
 Find Frear's SW BT, now down. We open and find good scribing.
Set Brass cap alongside cor. pipe and mkd: County Surveyors Office, 1962, ¼ S15|S14 T29S R6W.
New BT - 16" R.Fir bears S.27°W., 41.8 ft. scribed ¼ S15 CSBT

BLM resurvey by Peter Peterson and Daniel Berry under Group #750, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14611-12)

The ¼ sec. cor., perpetuated by Frear in 1919 when original corner evidence was existent, further perpetuated by Byron in 1962, monumented with an I.P. 1" dia., firmly set, protruding 4" above ground with 1962 DCSO brass cap.
from which a bearing tree marked by Frear in 1919
 A Fir 18" dia., bears S.69°E., 10 lks. dist., with healed blaze.
and a bearing tree marked by Byron in 1962
 A Fir 16" dia., bears S.27°W., 64 lks., with healed blaze.
and new bearing trees
 A W.Oak 9" dia., bears N.31°E., 30 lks. marked ¼ S14 BT.
 A Fir 9" dia., bears N.29°W., 116 lks. mkd. ¼ S15 BT

Fd. OK by DeGroot, July 1998 - M130-14