

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6468)

Set ¼ sec. post at average distance, from which
A B.Oak 20" dia., bears S.43°W., 100 lks. dist.
A W.Oak 10" dia., bears N.30°E., 72 lks. dist.

GL0 survey by W.H. Byars under Contract #152 dated June 3, 1871 (DCSO records Vol. 15 Page(s) 6490)

Set ¼ sec. post, from which
A Fir 6" dia., bears N.15°E., 33 lks. dist.
A W.Oak 10" dia., bears S.25°E., 49 lks. dist.

Frank Cain - For: J.F. Pefley - Wit: Hyman Huntly & J.M. Ledgerwood - Nov. 10, 1913 - Field Book 33 Page 20

Set Post marked ¼S and marked:
A W.Oak 14" dia., bears S.37½°E., 104 lks.
A Fir 10" dia., bears N.7°30'E., 29 lks.

A. Boyer, DCS - James Ware; Clay Darby - July 17, 1943 - (No record Source) (and "old" corner book, page 193)

Marked new BT
An 18" W.Oak N.28°E. 100 lks. to replace Fir which was dead. Corner is on S. side of County Road 5 ft. S. of road fence and 65 ft. W. of gate.

Douglas Co. Surveyors Office - Milo Godfrey; James Byron; Clete Putnam - June 15, 1961 - C.S. File 49/52-3

Found - 1" Iron pipe.
W.Oak now 18", S.37½°E., 68.6 ft. to face of tree, shows good scar.
W.Oak now 22" N.28°E., 66.0 ft. (to face of tree) shows good bark scribing "¼ S26 CS BT". Blaze & rescribe this tree.

Set Iron pipe with brass cap mkd: County Surveyors Office
T 29 S R 6 W
¼ $\frac{S\ 26}{S\ 35}$
1961

Did not scribe any new trees. Both Oak BTs are in good condition. No trace of Fir BT could be found.

continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. Brass cap & 2 BTs by H. Johnstone, 4/1978 - RM3-12	
DCS0-GIS Corner visitation - 8/17/2004 - Typed: 2/2/2011 - C.S. File 67/33-1	

Monument -	BC/IP - 1.25"
Comment -	(needs) rehab
Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - Feb. 16, 2011 - C.S. File 67/33-16	

Found -	2½" dia., brass cap (properly mkd) on a 1½" OD galv. IP protruding approx. 14" above ground. 1961 No OBTs fd. form 1854 or 1871 surveys. No 1913 Cain BTs fd. (SE BT fd by Boyer falls in Skyline Drv) An 18" W.Oak now a 24" DBH W.Oak with a fully healed single blaze, bears N.28°E., 67.3 ft. (rec. N.28°E., 66.0 ft.) record distance agrees to center of leaning trunk. 1941 Boyer
New -	17" DBH W.Oak scribed "¼ S35 CS" "BT" on a double blaze, bears S.75½°E., 80.5 ft. 8" DBH W.Oak scribed "¼ S35 CS" "BT" on a double blaze, bears S.5°E., 14.4 ft. 18" DBH D.Fir scribed "¼ S35 CS" "BT" on a double blaze, bears S.69°W., 54.8 ft.
Note -	Monument is in gently rolling mixed pasture and woodland just west of intersection of Boomer Hill RD. (Co. Rd. #40) and Skyline Drive. Per sketch, center line of Co. Rd. #40 at the intersection of Skyline Dr. & private Rd. bears N.70°E., 78.0' Decl. 15¾°E.
Fd. BC 12/2016 by Greg Lang, 2017-0012 A&B	