

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Doug. County Surveyors Office - R.B. Kimberling - F.C. Silagy  
- Dec. 1977 - C.S. File 59/42-28 - C.S. File 59/49 - M 68-47.  
-----  
Found - A 1"x36" I.P. with 1969 County Surveyors brass cap  
set 13" above ground, properly marked.  
I remove and reset to proportioned point between NE  
& SE sec. corner, Sec. 25. Cor. was orig.  
proportioned point between the NW cor. Sec. 19  
and the SW cor. Sec. 30. Needs re-surveyed since  
the SW cor. Sec. 19 was found.  
A 24" now 26" Ash, measured below the fork, bears  
N.18°E., 59.2'. (Rec. N.6°E., 52.5') with visible  
scribing "N1/16 CS BT" in partially healed double  
blaze.  
A 16" Cedar bears N.61°E., 65.5' with visible  
scribing "CS" in partially healed single blaze.  
Set - I reset brass cap 8" above ground in a 15" dia.  
mound of stone, at proportioned location, stamped  
"Reset 1977" above "1969".  
Set - A 5/8"x30" I.R. in a 15" mound of stone with alum.  
cap stamped "Douglas Co" 1977 Surveyor, at old  
location of brass cap. 1 1/2" alum. cap bears  
N.70°26'E. 13.05'.  
No new accessories. Corner is 0.8' north of east-west fence.  
Corner of fence to south & west bears S.87°E., 25.2'.

Fd. BC & 2 BTS May 2019 by D. Edwards M175-54

BLM dependent resurvey by Jeffrey O. Covington, Cadastral  
Surveyor, under Group No. 2940, surveyed June/Sept. 2019-  
(DCSO records Vol. 59 Page(s) 23995-6)  
-----  
The N 1/16 sec. cor. of secs. 25 and 30, established by  
Ingram, in December of 1977; and is accepted as the cor.;  
monumented with an iron post, 1" dia., firmly set, projecting  
15" above ground, in a mound of stone, 1 1/2 ft. base, 12" high,  
with a brass cap (properly) mkd.  
from which the BTs mkd. by Byron, in 1969, & reused by Ingram  
An ash, 32" dia., bears N.18°E., 59.0 ft., with illegible  
scribe marks visible on partially healed blaze.  
A cedar, 28" dia., bears N.61 1/4°E., 64.2 ft., with a healed  
blaze.  
Corner is located W., 25 ft., of fence cor., with wire fences  
extending S. and W.  
From this cor., a point erroneously established as the N 1/16  
sec. cor. of secs. 25 and 30, by Byron, in 1969; perpetuated  
by Ingram, in 1977...  
Continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 700260

PRIMARY CORNER DESCRIPTION N 1/16 Cor. Sec. 25; 30 T29-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

...This point was established using improper control and was not utilized for control in this survey, bears N.70°04'17"E., 12.98 ft.; monumented with an iron rod, 5/8" dia., firmly set, projecting 2" above ground, in a collar of stone, with an aluminum cap mkd. DOUGLAS CO. SURVEYOR 1977; from which the bearing trees mkd. by Byron

    An ash, 32" dia., bears N.6½°E., 52.0 ft., with illegible scribe marks visible on partially healed blaze.

    A cedar, 28" dia., bears N.59°E., 51.4 ft., with a healed blaze.

The 1969 iron post was reset by Ingram in its true position and the erroneously established position was perpetuated with an iron rod.