

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 24; 19 T29-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6421)

-----  
Set a ¼ post, from which,  
W. Oak, 12" dia., bears N.83°E., 67 lks.  
B. Oak, 10" dia., bears S.30°W., 64 lks.

Doug. County Surveyors Office - James W. Byron, Co. Surveyor - John M. Powell & crew - Feb. 1969 - C.S. File 54/79 - M 37-20.

-----  
Prorated ¼ corner  
Set - Brass cap at corner mkd. County Surveyor's R T29S R  
Office 6 1/4 5  
1969 W S24|19 W  
New BTs -10" D.Fir, S.87°W., 21.3' mkd: ¼ S24 CS BT.  
7" Oak, N.82°E., 16.1' mkd: ¼ S 19 CS BT.  
Note - North - South fence line bears East 13.0'.  
Corner 119.0' south of Boomer Hill Road.

Doug. County Surveyors Office - R.B. Kimberling - F.C. Silagy - Dec. 1977 - C.S. File 59/42-30 - C.S. File 59/49 - M 68-47.

-----  
Found - 1969 County Surveyors office brass cap set 14" above ground, properly mkd. Corner was proportioned between the NW cor. Sec. 19 and SW cor. Sec. 30. Needs resurveyed since the SW cor. Sec. 19 has been found.  
A 10" D. Fir, bears N.68½°W., 14.4' (rec. S.87°W., 21.3'), with a well healed double blaze.  
A 7" W. Oak, bears N.86°E., 23.9' (rec. N.82°E., 16.1') with visible scribing "S19" in partly healed double blaze.  
Set - I reset brass cap S.74°21'34"W., 8.85' cap is 6" above ground in a 18" mound of stone and mkd. "Reset 1977".  
I set a 1"x30" I.R. in orig. brass cap location with a 1½" alum. cap set 6" above ground in a 18" mound of stone and mkd. "Douglas Co." 1977 Surveyor.  
No new accessories. N-S fence bears East 20.3'.  
Boomer Hill Rd. bears North 124'.

Found OK by R. Brown, May 2003 - M142-17

continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 24; 19 T29-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

DCSO-GIS Corner visitation - 8/18/2004 - Typed: 2/2/2011 -  
C.S. File 67/33-1

-----  
Monument - BC/IP 1.25"  
Comment - (needs) rehab