

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 040060

PRIMARY CORNER DESCRIPTION SE Cor. I Wells DLC #40

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Bowman and Burnett, under Contract dated Sept. 1855</p> <p>-----</p> <p>Set a post as per instructions, from which A B.Oak 12" dia., bears N.50°W., 40 lks.</p>
<p>Douglas Co. Surveyors Office - Ben B. Irving - For: Request by County Court, Rd. #38 survey - 1954 - C.S. File 46/36</p> <p>-----</p> <p>Corner renewed from old BT, N.50°W., 26.4 ft. BT is standing but dead and corner is OK with old barbed wire fence corner. Set a 5/8" x 30" Iron rod for the corner. Blazed and scribed two trees: Red Fir 12" dia., South, 35.6 ft. mkd. S.E. Cl. 40 CSBT Red Fir 16" dia., N.79°W., 52.3 ft. mkd. SE Cl 40 CSBT.</p>
<p>BLM survey by Theilsen in 1955, ( DCS0 records, Vol. 28 Pg. 11772), said there was no remaining evidence of the original corner.</p>
<p>Douglas Co. Surveyors Office - John M. Powell; W. Penley; J. Heritage - Oct. 19, 1970 - C.S. File 49/139-132</p> <p>-----</p> <p>Found - As noted, Oak, N.50°W., 26.4 ft. (orig.) Possible old axe work. 12" D.Fir, now stump, South, 35.6 ft. scribe visible "BT" 16" D.Fir, now stump, N.29°W., 52.3 ft. scribe visible "BT". 5/8" Iron rod at corner. Bent. Set Brass cap at cor. mkd: County Surveyor's T 29 S R 7 W Office 1970 S.E.   DLC 40  </p> <p>New BTs -7" D.Fir N.15°W., 51.4 ft. scribed "SE DLC 40 CS BT" 11" D.Fir S.60°W., 17.7 ft. scribed "SE DLC 40 CSBT" This corner lies on top of ridge on south side of old road, 14 ft. N. and 22 ft. west to center of road. Also call of 2 chs. seems to hit good. Appears to line up with N-S line in valley to the North.</p>
<p>BLM resurvey by Berry &amp; Popken, under Group #316, Survey, 1973, (DCS0 records Vol. 39 Page(s) 15807) Fd. 1970 County brass cap, orig. BT, and DCS0 Fir BTs.</p>
<p> </p>