

PRIMARY CORNER DESCRIPTION AP on Township Line

Alias 919010 Description AP 1 TR 47 & AP 4 TR 63, T28-7
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Cadastral Engineer - under special Instructions, dated April 18, 1924 - (DCSO records Vol. 14 Page(s) 5909)

Intersect the W bdy. of the WM McCullough DLC #56, 13.55 chs. S.0°30'W, from the NW cor. of Cor. #2 (TR 63).

At the point of intersection

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for cor. #4 of this survey, identical with cor. #1 of TR #47, T29-7 with brass cap mkd:

TR63|
AP 4|
AP 1|
TR47|
1924

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 7/15/1999 - C.S. File 66/12-24

Found - 2½" brass cap on a 1" O.D. x 36" long iron pipe, is found out of the ground. 1924

Set - 1924 is set at a position determined from a 1924 GLO monument to the West & a 5/8" IR per M 71-8 north of corner. "DCSO RESET 1999" added to brass cap.

US GENERAL LAND

TR63|DCSO
AP 4|RESET
AP 1|1999
TR47|

OFFICE SURVEY

5/8" I.R. bears N.0 3/4°E., 217.7 ft. (Agrees with calc. rec. per M71-8)

1961 DCSO BC/IP (T28S R7W SW cor. Sec. 31) Reset 1999, bears N.88 3/4°W., 65.3 ft. (Agrees well with GLO) 1924 rec)

5" dia., W.Oak double blazed and scribed "X CS BT" bears N.4°W., 59.7 ft.

Note - N-S fence line is 10 ft. East of corner. Area appears to have been bull dozed several times in past.

See next page for calculations used in setting this corner.

