

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. Sec. 32 Only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6522)</p> <p>-----</p> <p>Set ¼ sec. post, at proper distance from which; A B. Oak, 15" dia., bears N.50°W., 25 lks. A Red Fir, 30" dia., bears S.80°W., 75 lks.</p>
<p>Re-establishment of corners - Fred Mensch , U.S. Deputy Surveyor - under date of April 18, 1924 (DCSO Vol. 14 Page 6039)</p> <p>-----</p> <p>Intersect the point for ¼ sec. cor., located by measurement from the orig. bearing trees. At the exact cor. point Set an iron post, 3' long, 1" dia, 28" in the ground, for ¼ sec. cor. of sec. 32 only, with brass cap mkd: <u>¼ S32</u> 1924</p> <p>from which (the orig. bearing trees) A Black Oak, 24" dia., bears N.34°W., 25 lks. (not N.50°W.) marks show on the overgrowth. A Fir stump, bears S.81°W., 75 lks. (not S.80°W.) New bearing trees A Fir, 6" dia., bears N.38°E., 13 lks. mkd: ¼ S32 BT. A Fir, 8" dia., bears N.14°W., 20 lks. mkd: ¼ S32 BT.</p>
<p>Douglas Co. Surveyors Office - Ben B. Irving, Co. Surveyor - James Byron - Ray Irving - Work done under order of County Court - Feb. 1954 - C.S. File 46/36</p> <p>-----</p> <p>Corner positively identified. Brass cap at corner and 6" Red Fir, N.38°E., 13 lks. standing. Blazed and scribed 2 trees: 8" Red Fir, N.28°W., 4.4 ft., mkd: T29S ¼ S32 CS BT 10" Red Fir, N.51.°E., 12.0 ft., mkd: T29S ¼ S32 CS BT</p>
<p>Douglas Co. Surveyors Office - James W. Byron, Deputy & Crew - June 1962 - C.S. File 49/139</p> <p>-----</p> <p>Found - Brass Cap set in 1924. 8" R. Fir, scribed by B. Irving in 1954, now 5' snag, scribing vis. 10" R. Fir, N.51°E., 12.0 ft. OK New BT - 7" R. Fir, N.62°W., 20.8' scribed S¼ S32 CS BT.</p>
<p>FD Ok BLM resurvey by Peterson, 1988, (DCSO records Vol 49 Pages 18815-16)</p> <p>-----</p> <p>Found OK by T. Baker, Oct. 2000 - M136-9 A&B</p>