

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6532)

Set 1/4 sec. post, from which
A B.Oak, 12" dia., bears S.48°W., 75 lks. dist.
A B.Oak, 12" dia., bears N.87½°E., 48 lks. dit.

GLO survey by Hans W. Thielsen, under Group #346, Surveyed, April/May 1957 - (DCSO records Vol. 28 Page(s) 12157)

Point for the 1/4 sec. cor. of secs. 15, 16, at proportionate distance; there is no remaining evidence of the original corner.
Set an Iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:
T29S R7W
1/4
S 16*S 15
1957

from which
A Fir 15" dia., bears N.53°E., 74 lks. mkd. 1/4 S15 BT.
A Fir 16" dia., bears S.58°W., 52 lks. mkd. 1/4 S16 BT.
The 1/4 sec. cor. is located on a spur, slopes SW.

BLM resurvey by John M. Jelley, under Group #346, Surveyed, Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14294)

Point for the 1/4 sec. cor. of secs. 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.
From this point the 1/4 sec. cor. erroneously reestablished by Thielsen, in 1957, bears South, 0.099 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, and at the corner point
Reset the iron post, 36" long, 1" dia., 28" in the ground with brass cap marked:
T 29 S R 7 W
1/4
S 16*S 15
1966
1957

from which bearing trees marked by Thielsen in 1957:
A Fir 17" dia., bears N.60°E., 68 lks. with healed blaze.
A Fir 16" dia., bears S.50°W., 57 lks. with healed blaze.

Fd. OK, May 1981, Howard Johnstone, M 87-75

continued next page

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2270, Surveyed May/Aug. 2009 - (DCSO records Vol. 57 Page(s) 22752)

The 1/4 sec. cor. of secs. 15 and 16, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of a BT mkd. by Thielsen in 1957

A fir, 21" dia., bears N.60°E., 44.9 ft., with a healed blaze.

A sawed fir stump, 20" dia., bears S.50°W., 37.6 ft., with a healed blaze.

and a new bearing tree

A fir, 5" dia., bears N.52°W., 22.6 ft., mkd. 1/4 S16 BT.

Fd as per 2009 BLM resurvey - set 6 ft. steel post 2 ft. S.2°W., by D. Edwards - 4/2014 - M167-73