

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6532)

Set 1/4 sec. post, at average distance, from which
A B.Oak 8" dia., bears N.35°E., 42 lks.
A B.Oak 6" dia., bears S.75°W., 50 lks.

BLM resurvey by Hans W. Thielsen, under Group #346 - Surveyed April/May 1957 - (DCSO records Vol. 28 Page(s) 12155)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 1" dia., 18" in the ground to solid rock, and in a mound of earth and stone to top, with brass cap marked:
T29S R7W
1/4 $\frac{S\ 15}{S\ 22}$
1957

from which
A Fir 13" dia., bears N.16°E., 96 lks. mkd. 1/4 S15 BT.
A Fir 23" dia., bears S.53°W., 150 lks. mkd. 1/4 S22 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell; Wm. Stoffel - July 1962 - C.S. file 49/139-89

Found - Brass cap at cor. and both BTs, now dead.
New BTs -8" W.Oak bears N.1°E., 47.8 ft. scribed 1/4 S15 CS BT.
8" Cedar bears S.47 1/2°W., 81.0 ft. scribed 1/4 S22 CS BT.

BLM resurvey by John Jelley, under Group #346 - Surveyed Aug/Oct. 1966 (DCSO records Vol. 34 Page(s) 14293)

Point for the 1/4 sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.
From this point, the 1/4 sec. cor. of secs. 15 and 22, erroneously reestablished by Thielsen in 1957, bears, South, 0.098 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, and at the corner point:
Reset the iron post, 36" long, 1" dia., 18" in the ground, to solid rock, and in a mound of earth 4 ft. base to top, with brass cap marked:
T 29 S R 7 W
1/4 $\frac{S\ 15}{S\ 22}$
1966
1957

(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which bearing trees marked by J.W. Byron, Deputy County Surveyor, in 1962
An Oak 8" dia., bears North, 62 lks. dist., with scribe marks $\frac{1}{4}$ S15 CS BT visible on partly healed blaze.
A Cedar 9" dia., bears S.55°W., 129 lks. dist., with scribe marks $\frac{1}{4}$ S22 CS BT visible on partly healed double blaze.
I destroy the marks on the 1957 bearing trees.

Fd. Brass cap & 2 BTs, Oct. 1984, Howard Johnstone, M 97-54

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2270, Surveyed May/Aug. 2009 - (DCSO records Vol. 57 Page(s) 22751-2)

The $\frac{1}{4}$ sec. cor. of secs. 15 and 22, monumented with an iron post, 1" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd.
from which BTs mkd. by Byron, in 1962
An oak, 13" dia., bears North, 40.9 ft., with a healed blaze.
A cedar, 15" dia., bears S.44°W., 85.1 ft., with a healed double blaze.
Corner is N., 8 ft. from the base of a rock shelf, base bears N.60°E. and S.60°W., on a N. slope