

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Pages 6528-29)

-----  
Set a post cor. of secs. 2, 3, 10 and 11, from which  
A W.Oak 24" dia., bears S.25°W., 105 lks. dist.  
A B.Oak 18" dia., bears S.10°E., 225 lks. dist.  
A W.Oak 20" dia., bears N.15°E., 62 lks. dist.  
A W.Oak 36" dia., bears N.45°W., 50 lks. dist.

Douglas Co. Surveyors Office - J.W. Cole - Nov. 23, 1923 - Vol. 3 Pg. 172; C.S. File 6/33; C.S. File 35/46 and C.S. File 4/60

-----  
I renewed this corner from the original BTs.  
Set a sandstone 8" x 10" x 15" with cross on top and West sides, from which  
A W.Oak N.15°E., 40.9 ft. alive and bearing scars.  
A W.Oak N.42°W., 33.0 ft. alive and bearing scars.  
A W.Oak S.23°W., 69.5 ft. alive and bearing scars.  
A B.Oak S.6°E., 148.6 ft., dead stub.  
New BT - 8" W.Oak S.50°E., 10 ft.

GLO resurvey by Hans W. Thielsen under Group #346, Surveyed, April/May 1957 - (DCSO records Vol. 28 Page(s) 12153)

-----  
The cor. of secs. 2, 3, 10 and 11, remonumented by the County Surveyor in 1923 with a sandstone, 15 x 10 x 8 ins., now shattered with no marks remaining, from which the remaining original bearing trees:

A W.Oak 30" dia., bears N.15°E., 62 lks. dist., plainly blazed and healed.  
A fallen W.Oak 26" dia., bears S.25°W., 105 lks. dist., with partial scribe marks visible on unhealed blaze.  
A W.Oak 38" dia., bears S.50°E., 16 lks. dist., plainly blazed and healed.

and a tree marked in 1923

A W.Oak 10" dia., bears S.50°E., 16 lks. dist., plainly blazed and healed.

At the cor. point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T29S R7W  
S 3 S 2  
S 10 S 11  
1957

from which a new bearing tree

A Fir 8" dia., bears S.53°W., 81 lks. dist., mkd. T29S R7W S10 BT.

(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit the shattered sandstone at the base of the iron post as a memorial.

Fd. OK, Sept. 1980, Glenn Baughman, M 85-35

BLM resurvey by Jelley and Rogers, under Group #1044, Surveyed, Jan/April 1981 - (DCSO records Vol. 43 Page(s) 16673-74)

-----  
From the sec. cor., perpetuated and recorded by Cole in 1923, recorded by Boyer in 1957 and recorded by Glenn Baughman LS #536 in 1980, monumented with an iron post, 2" dia., firmly set, projecting 4" above ground, with brass cap mkd.  
T 29 S R 7 W  
        3 2      
    10 11  
    1957

from which the remains of the original bearing trees  
  A W.Oak 29" dia., bears N.15°E., 62 lks. dist., with healed blaze.  
  A root hole, bears S.25°W., 105 lks. dist., with a down Oak alongside, size indeterminate, no marks visible.  
  A W.Oak 40" dia., bears N.45°W., 50 lks. dist., with healed blaze.  
and a bearing tree by Cole  
  A W.Oak 10" dia., bears S.50°E., 18 lks. dist., with healed blaze. (Rec. 16 lks.)  
and a new bearing tree  
  A Fir 15" dia., bears S.45°W., 50 lks. dist., mkd. T29S R7W S10 BT.  
From this point, a fence corner bears S.45°W., 0.04 chs. dist., fences extending S. and E.