

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & S. 31, T28-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page 5795)

Set ¼ sec. post, from which
A Fir 20" dia., bears N.58°E., 3 lks. dist.
A Fir 20" dia., bears S.20°E., 7 lks. dist.

BLM Resurvey by John M. Jelley, Cadastral Surveyor, under Group #552, surveyed July 1964 - (DCSO records Vol. 32 Page(s) 13568-69)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 28 S R 8 W
¼ S 31
S 6
T 29 S
1964

from which
A Fir 16" dia., bears N.49 3/4°E., 134 lks. dist. mkd. ¼ S31 BT.
A Fir 6" dia., bears S.49 3/4°W., 166 lks. dist. mkd. ¼ S6 BT.
From this point, an iron pipe 3/4" dia., 3" above ground, firmly set, bears S.6°45'E., 0.10 chs. dist.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Aug. 5, 1992 - C.S. File 64/31

Found - 3½" BLM brass cap, 1964, properly mkd., on a 2½" O.D. Iron pipe protruding 3" above ground.
6" now 17" dia. D.Fir with a fully healed single blaze, bears S.50 3/4°W., 109.4 ft.
16" now 24" dia. D.Fir with a fully healed blaze bears N.50 3/4°E., 88.4 ft. (Rec. N.49 3/4°E., 88.4 ft.)
3/4" O.D. Iron pipe, flush with ground, bears S.6 3/4°E., 6.6 ft. (agrees w/rec., C.S. File 23/47?). Remnants of old fence from West coming into I.P.
No original BTs found.
New BT - 8" dia. W.Fir, double blazed and scribed "¼ S6 CS BT", bears S.72°E., 41.0 ft.

Fd. OK by G. Lang, Feb. 2000 - M134-30
Fd. Ok by Ed Farr, 11/2006 - M153-25