

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6598)

-----  
Set ¼ sec. post, from which  
A Fir 12" dia., bears N.78°E., 17 lks. dist.  
A Fir 10" dia., bears S.32°W., 13 lks. dist.

C.W. Crocker for Oregon State Hwy. Dept. - Sept/Dec. 1939 - C.S. File 16/55

-----  
Set a 3/4" x 30" Iron rod from original BT.  
A 12" Fir N.78°E., 17 lks. is stump in poor condition.  
A 10" Fir S.32°W., 13 lks. has been cut open.  
Tree in fair condition.  
Blazed and scribed two new trees as follows:  
A 24" Fir bears S.43°30'W., 25.8 ft.  
A 40" Fir bears S.78°15'E., 48.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-31

-----  
Found - Orig. 10" now 26" Fir, down, open fce, shows good scribing, S.32°W., 8.6 ft.  
1/2" Iron rod at corner.  
40" Fir, now dead, shows good bark scribing "¼ S9 CS BT". This BT and iron rod set by Boyer in 1939.  
Stump hole that checks bearing and distance for Boyer's SW. BT.  
I do not set brass cap at corner.  
New BTs- 9" W.Fir bears S.42°W., 48.3 ft. scribed ¼ S8 CS BT.  
14" Cedar bears S.25½°E., 88.4 ft. scribed ¼ S9 CS BT. Scribed 5.0 ft. above ground.

Fd. OK, June 1980 by R. Hendrick - M 84-19

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 17003)

-----  
The ¼ sec.cor., perpetuated and recorded by Boyer in 1939 and futher perpetuated and recorded by Byron in 1958, monumented with an iron rod, 3/4" dia., firmly set, projecting 2" above ground, from which the remains of an original bearing tree:  
A root hole bears S.32°W., 13 lks. dist. with a down Fir 15" dia., with fragmentary scribe marks visible on decayed blaze.

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

and a bearing tree mkd. by Boyer  
A Fir snag 50" dia., bears S.78¼°E., 75½ lks. dist. with  
fragmentary scribe marks visible on bark blaze.  
and bearing trees mkd. by Byron:  
A Cedar 19" dia., bears S.25½°E., 134 lks. dist., with  
healed blaze.  
A W.Fir 15" dia., bears S.40°W., 73 lks. dist., with  
healed blaze.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,  
with brass cap mkd:           T 29 S   R 8 W  
  1/4  
  S 8 | S 9  
  1980  
from which new bearing trees:  
A W.Fir 9" dia., bears S.46½°E., 5½ lks. dist. mkd. ¼ S9  
BT.  
A W.Fir 7" dia., bears N.46°W., 22½ lks. dist. mkd. ¼ S8  
BT.

Fd. OK, May 1993 by L. Jay - M 117-22  
Fd. OK, Aug. 1995 by M. Smalley - M 119-69