

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6583-84)

Set ¼ sec. post, from which
A Fir 24" dia., bears N.59°E., 20 lks. dist.
A Laurel 15" dia., bears S.50°E., 32 lks. dist.

(Corrective resurvey)- Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 - (DCSO records Vol. 14 Page(s) 6033)

Intersect the point for ¼ sec. cor., located by measurement and record bearing from the original NE. bearing tree.
At the exact cor. point
Set an iron post 3 ft. long, 1" dia., 28" in the ground for ¼ sec.cor., with brass cap marked: ¼ $\frac{S 1}{S 12}$
1924

from which original bearing tree:
A Fir 36" dia., bears N.59°E., 20 lks. dist., marks plain on the bark.
New bearing trees:
A Maple 12" dia., bears S.39°E., 48 lks. dist. mkd. ¼ S12 BT.
A Fir 16" dia., bears N.71°W., 51 lks. dist. mkd. ¼ S1 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 1966 - C.S. File 54/38-9

Found - GLO brass cap at ¼ cor., properly mkd. in 1924.
36" Fir, now stump, N.59°E., 13.2 ft.
16" Fir, now down, N.71°W., 33.9 ft., shows good scar.
12" Maple now 16", S.39°E., 31.7 ft., shows good scar.
New BTs- 11" Maple N.18°E., 37.5 ft. mkd. ¼ S1 CS BT.
17" D.Fir S.86°W., 23.0 ft. mkd. ¼ S12 CS BT.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy - Frank Silagy; Terrie Plouff, crew - Oct. 2, 1978 - C.S. File 60/17-9

Found - Properly mkd. 1924 GLO brass cap on a 1" I.P., firmly set, extending 8" above ground.
(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The remains of an orig. BT, a 24" Fir, now a badly decayed 36" stump with no markings, bears N.59°E., 13.2 ft.
No trace found of orig. SE. Laurel BT.
A 1924 BT, a 12" now 16" Maple, alive with well healed single blaze, bears S.39°E., 31.7 ft.
A 16" D.Fir, now blown down with well healed single blaze, bears N.71°W., 33.7 ft.
An 11" now 13" Maple, alive with scribing "¼ S1 CS" visible on partially healed double blaze, bears N.21°E., 34.6 ft. (Rec. N.18°E., 37.5 ft.)
A 17" D.Fir, now an 18" blowdown with partially healed double blaze, bears S.86°W., 23.0 ft.
No new monument set.
New BT - 22" D.Fir scribed "¼ S1 CS BT" on a double blaze, bears N.84°E., 29.7 ft.
Corner located beneath 36" Fir windfall.

FD. BC & 2 BTs by Ken Hoffine, 8/2007 - M154-14