

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec cor to 12 & 13 only, East

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, Contract #57 dated April 12, 1855 (DCSO records, Vol. 16 Page 6570)

Set post, cor. sec. 7, 18, 12, & 13, from which:

- A B. Oak, 6" diam., bears N.4°W., 94 lks.
- A B. Oak, 9" diam., bears N.56°E., 39 lks.
- A B. Oak, 20" diam., bears S.45°E., 77 lks.
- A B. Oak, 10" diam., bears S.5°W., 220 lks.

Re-establishment of corners - Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 (DCSO Vol. 14 Page 6010-11)

Intersect the point for the Hathorn cor. of secs. 7, 12, 13, & 18, located by measurement from the original bearing trees. The marks are grown over on all these trees and are not opened, blazes are plain.

At the exact cor. point

Set an iron post, 3 ft. long, 2" diam., 28" in the ground, for cor. of secs. 12 & 13 only, with brass cap marked

T29S:

S12:

S13:

R8W:

1924

from which (the original bearing trees)

- A B. Oak, 20" diam., bears N.59°E., 39 lks.
- A B. Oak, 40" diam., bears S.45°E., 77 lks.
- A B. Oak, 24" diam., bears S.4°W., 223 lks.
- A B. Oak, 14" diam., bears N.4°W., 94 lks.

New bearing trees:

- A B. Oak, 14" diam., bears S.57°W., 62 lks., mkd. T29S R8W S13 BT.
- A B. Oak, 12" diam., bears N.5°W., 34 lks., mkd. T29S R8W S12 BT.

James W. Byron, Dep. Co. Surveyor - John Powell & Dale McFarland - May/June 1962 - C.S. 49/139-72

Found - Brass cap at corner & Both BTs. SW. BT. in poor condition.

New BT - 19" Pine, bears S.62°W., 10.3 ft. scribed S13 T29S R8W CS BT.

Corner Fd. OK, BLM resurvey by Akin, Shaner and Jelley, under Group #s 808, 858 and 860. Surveyed June 26, 1973/April 7, 1976 (DCSO records, Vol. 39 Page 15759)
(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13 only, East

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Larry E. Monrean, Do. Co. Surveyors Office - P.L. Earle & K. Cheney - Jan/Feb 1977 - C.S. 59/29-24

Found - 1924 GLO brass cap properly stamped.

BTs per 1855 Hathorn Survey:

A B. Oak, 20" now 52", bears S.45°E., 50.9 ft. tree has paint blaze.

An Oak, down and rotted bears S.56°E., 25.7 ft. no scribing found.

BTs per 1924 GLO Survey

An Oak down and rotted bears S.57°W., 40.9 ft no scribing found, outlying of blaze visible.

A B. Oak, 12" now 14" bears N.5°W., 22.4 ft. blaze rotting out.

BT Per James Byron:

A 19" now 26" pine bears S.62°W., 10.3 ft. Tree has well healed double blaze.

Renewal:

I double blaze and rescribe the 12" B. Oak scribed in 1924. Tree bears N.5°W., 22.4 ft. I blaze the area to the East of the old blaze and scribe "T29S R8W S12 CS BT".