

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & S. 1, T30-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7373)

Set ¼ sec. post, from which
A Fir 12" dia., bears S.38°W., 25 lks. dist.
A Chinquapin 12" dia., bears N.28°E., 50 lks. dist.

A. Boyer, Deputy Co. Surveyor - Wit: J.N. Nelson; J.W. Priest - Feb. 24, 1943 - Vol. 4 Page 96

Set midway between SE. and SW. corners. Drove a 2" flue pipe, from which
A 30" Fir bears S55°W., 46.5 ft.
A 12" Fir bears N.18°E., 40.0 ft.
Original BTs could not be found. The above trees are new ones.

Survey by Ronald E. Stuntzner - For: Dr. & Mrs. Keizer - Feb. 1977 - M 63-61

Found - 2" I.P. at S. ¼ Sec. 36.
30" D.Fir S.15°W., 46.5 ft., windfall.
Remains of 12" D.Fir N.18°E., 40.0 ft.
New BTs- 14" W.Fir S.83°W., 30.6 ft., tagged.
12" W.Fir N.13°E., 14.5 ft., tagged.

Fd. OK, Feb. 1997 by D. Bentz - M 126-39