

TOWNSHIP 31 RANGE 01E POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO dependent resurvey by Leonard Carter, Public Land Surveyor, under Group No. 175, surveyed Sept./Nov. 1936 - (DCSO Vol. 46 Page(s) 17660)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4 S 2
S 11
1936

from which

A fir, 37" dia., bears N.59°E., 18 lks., mkd: 1/4 S2 BT.

A fir, 16" dia., bears S.10°W., 108 lks., mkd: 1/4 S11 BT.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - July 1, 1985 - C.S. File 62/28-12

Found - 1936 GLO disk on a 1" IP bent northerly, under downed orig. NE bearing tree, properly marked. 22" now 27" dia. W.Fir with a single fully healed blaze bears S.10°W., 71.3 ft. Agrees with record. (Orig.)

37" now down and badly rotted fir, no scribing found. A depression with roots present bears N.59°E. , 11.9 ft. agrees with record. Orig.)

Set - Monument was dug out and orig. position referenced. Monument was straightened and returned to orig. plumb position. Monument protrudes 1" above a 3 ft. mound of stone set around iron pipe.

New BTs- 11" W.Fir double blazed and scribed "1/4 S11 CS BT" bears S.75°W., 44.0 ft.

36" W.Fir double blazed & scribed "1/4 S2 CS BT" bears N.38°W., 94.2 ft.

17" W.Fir double blazed & scribed "1/4 S2 CS BT" bears N.81°E., 22.4 ft, to root crown. Tree leans NW.

Note - Corner lies near bottom of ravine approx 250 ft. north of road. (USFS 2925-700)