

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 5 & 6

Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy -
Terrie Plouff - Karen Mosley - Feb. 26, 1981 - C.s. 61/19-9

Found - From 1905 resurvey, a red fir, 30" diam. marked as
the corner tree is now a 34" diam. approx 4 foot
tall rotted fir stump, an open and burned blaze
on its west face has the scribing 4 S6 visible,
the east face is burned and has a blaze but no
scribing is visible.

A 1968 County Brass cap, 2½" on a 1" I.P. protrudes
15" above ground & bears North 2.0 ft. from above
corner. Cap marked "County Surveyor T30S R1W ¼ 6
5 1968".

No accessories from orig. 1857 survey are found. These were
destroyed in 1905 resurvey.

Found - From 1905 survey, A W.Fir, 18" now an 18' dia.
rotted fir stump bears N.80°W., 15.8 ft. from
1905 corner tree. Has a single blaze with
scribing ¼ S6 BT visible.

No evidence of other 1905 BT is found.

From 1968 Ren. two trees are found; bearings and distances
are checked from the brass cap monument:

An 11" W.Fir now a 15" DBH W.Fir bears S.84°E., 45.4
ft. (Rec. S.89°E., 46.1 ft.) Tree has partially
healed double blaze with the scribing S5 CS
visible.

An 8" W.Fir now a 12" DBH W.F bears S.56°E., 32.6
ft. (Rec. S.61°E., 32.6 ft.) Thee has partially
healed double blaze with some illegible scribing
visible.

Note - Variation of bearing and distance from record in the
preceding two bearing trees probably resulted
from an improperly declinated compass and an
improperly reduced slope distance.

A 6" D.Fir now a 6" DBH D.Fir bears S.32°W., 22.4
ft. (Rec. S.32°W., 21.9 ft.) Tree has double
blaze with scribing 1/4 S6 BT visible. 1979

Monument location is accepted. The following markings are
added to the brass cap monument "W ↯" The arrow points south
to the corner tree.

All accessories are tagged with new DCSO bearing tree tags.

FD. BC with BTs, H. Pieske - 9/1993 - M117-62

continued next page

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 5 & 6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ron Quimby, LS 1654 - Ryan Palmer - J. Leonard - 11/25/2009 -
C.S. File 65/66-54

Found - Orig. corner stump with spike.
DCS0 brass cap (properly marked)
12" Fir S.32°W., 22.4 ft.
11" Cedar N.42°W., 10.1 ft. (RFP 10/93 tag)
21" Fir S.63°E., 30.8 ft.
20" Fir S.89°E., 44.9 ft.

Russell Badgley - For: USDA Forest Service - 7/2021 - M179-77

Found - The original corner tree, by FRED MENSCH IN 1904,
per contract #757, now a rotting 34" stump, with
an existing spike in the top and remnants of a
blazes

From which references by the DCS0 in 1968 -

A 1" iron post, by the DCS0 in 1968 per C.S. file
54/59,-26, firmly set in a mound of stone,
projecting 12", bears N.36°06'10"W., 1.69 ft.,
with a 2½" DCS0 brass cap, (properly) mkd

A 22" D.Fir S.89°00'E., 44.9 ft. w/healed double
Blaze (S.89°E., 44.9 ft)

A 22" D.Fir bears S.61°15'E., 31.1 ft w/healed
double blaze (S.63°E., 30.8 ft)

And a BT by Baughman in 1979

A 13" D.Fir bears S.32°45'W., 21.5 ft. w/healed
double blaze (S.32°W., 22.4 ft)

And BTs by others

A 12" Cedar bears N.40°00'W., 9.8 ft w/healed double
blaze (N.42°42'W., 10.1 ft.)

A 13" D.Fir bears S.61°E., 13.3 ft. w/healed double
blaze (no record)

NAD83(2011)

Lat: 42°59'50.57875"N

Long: 122°51'45.72064"W