

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23 & 26; East only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 16 Page(s) 6736)

Point of intersection with line extended E from cor. of secs. 22, 23, 26, & 27
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for cor. of secs. 23 & 26, with brass cap marked

T30S |
S23 | S24
S26 |
R1W |
1923

from which
A fir, 24" dia., bears S.3½°W., 131 lks., mkd: T30S R1W S26 BT.
A cedar, 6" dia., bears N.52°W., 111 lks., mkd: T30S R1W S23 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones - W. Penley - Jan.2, 1968 - C.S. File 54/59-15

Found - GLO Brass Cap at Sec. Cor. properly marked in 1923. 24", now 32" D.Fir, S.3½°W. 86.5 ft., shows good scar.
6" now 19" Cedar, N.52°W. 73.3 ft., nothing visible.
As trees are far away and one south of other corner, I mark new BTs:
2" Cedar N.23°W. 8.7 ft. mkd. T30S R1W S23 CS BT.
6" D.Fir S.20°W. 4.3 ft. mkd. T30S R1W S26 CS BT.
Note - This corner lies 59.4 ft. north of section corner to sections 24 and 25 only, which was found in good condition.