

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 100201

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only, T30-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6773) and (dup. info. on Page 6906)

Set a stone 20x16x7 ins., 15" in the ground for cor. to secs. 25, 30, 31 and 36 marked with 5 notches on N. and 1 notch on S. edges, from which
A Cedar 11" dia., bears N.67 3/4°E., 27 lks. dist. mkd. T30S R2W S30 BT.
A Hemlock 24" dia., bears S.30°E., 52 3/4 lks. dist. mkd. T30S R2W S31 BT.
A Maple 14" dia., bears S.31¼°W., 27 lks. dist. mkd. T30S R3W S36 BT.
A Fir 10" dia., bears N.45½°W., 26½ lks. dist. mkd. T30S R3W S25 BT.

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Pgs 6867-68)

The Sec. cor., which is a granite stone 6x12x7 ins. above ground, firmly set, marked and witnessed as described by the surveyor general.
Obliterate marks on this corner referring to secs. 30 and 31. (Corner established for 30 & 31 bears S.1°9'E. 70 lks.)

Arthur Boyer, Douglas Co. Surveyor - Geo. Stone and Donald Stone, witnesses - Jan. 30, 1939 - C.S. File 16/11

Found rock loose and out of place and Fir tree to the NW. gone. Reset rock as well as could be done and drove steel auto axle from 3 BTs which are standing. Marked new BT:
A 16" Fir N.52°45'W., 23.0 ft. mkd. S25 T30S R3 CS BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - May 7, 1958 - C.S. File 49/86-1

Found - Boyer BT, 16" now 24" Fir, N.52°45'W., 23.0 ft.
Orig. 11" now 20" Cedar N.67 3/4°E., 17.8 ft.
Both BTs have good scribing, are alive and in good condition.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 3 W
S 25 | S30 R2W
S 36
1958
New BT - 72" R.Fir bears N.33°E., 14.5 ft. "S30 T30S R2W CS BT, bark scribed.

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 100201

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only, T30-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: N. Fromdahl & L. Heddens - 6/2020 - C.S.
File 65/106-27

Found - DCS0 Brass cap, properly marked (OFFICE is upside
down compared to the rest of the stamping)
28" rotted fir stump N.53°W., 23.0 ft.
23" rotted cedar stump N.68°E., 17.8 ft.
72"x4' fir stump N.33°E., 14.5 ft. (face burnt out
& hollow)
¾" I.Pipe S.1°E., 46.16 ft.
New - 13" Hemlock S.30°E. 15.6 ft scribed: T30S R3W S36 BT
11" Hemlock S.53°W. 22.8 ft scribed: T30S R3W S36 BT