

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1, T31-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7704)

I remove a temp. post, and Set a stone, 15x10x8 ins., 10" in the ground for closing cor. to Tp. 31 S., Rs. 2 and 3 W., marked C C on S. face, with 6 notches on SE. and W. faces, from which

- A Fir 6" dia., bears S.20 $\frac{3}{4}$ °E., 56 lks. mkd. T31S R2W S6 BT
- A Fir 30" dia. bears S.42 $\frac{1}{2}$ °W. 58 $\frac{1}{2}$ lks. mkd. T31S R3W S1 BT
- A Hemlock 10" dia., bears N.18 $\frac{1}{2}$ °W., 34 lks. mkd. CC T31S Rs 2 and 3 W BT.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Greg Quibell & Terrie Plouff - Oct. 20, 1981 - C.S. 61/29-15

Found - Orig. 15"x10"x8" now 14"x7"x5" stone marked with CC on S. face & grooves on the S., E., and W. faces, firmly set with top flush with ground.

Orig. 30" now 36" Fir with good scar bears S.42 $\frac{1}{2}$ °W., 38.0 ft. (Rec. 38.6 ft.)

Orig. 10" now 21" Hemlock with good scar bears N.18 $\frac{1}{2}$ °W., 22.2 ft.

At the exact location of the orig. stone, I set a brass cap protruding 9" out of ground, mkd: Douglas County Surveyor CC T30S R2W S31 T31S R3W S1 1981. Replaced stone on S. edge of cap.

New - Set PK nail and scribed BT in base of orig. 30" now 36" Fir on downhill side of tree, bears S.39 $\frac{1}{2}$ °W., 37.1 ft. to nail.

Set PK nail and scribed BT in base of orig. 10" now 21" Hemlock on downhill side of tree, bears N.17°W., 21.8 ft. to nail.

Set PK nail and scribed BT in base of 32" Fir on downhill side of tree bears N.81°W., 31.0 ft. to nail.

Set PK nail and scribed BT in base of 12" Hemlock on downhill side of tree bears S.19°E., 20.8 ft. to nail.

All of the BTs for this corner will be cut in future timber sale.

DCSO-GIS Corner visitation - 2/25/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

Monument - 1 $\frac{1}{4}$ " IP/BC Comment - rehab

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 133111

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1, T31-3

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

Found - Brass cap per 1981 DCSO renewal
38"x3' Fir stump S.39°W., 37.1' (To nail) healed
face
24"x4' Hemlock stump N.17°W., 21.8' (To nail) healed
face
36"x3' Fir stump N.81°W., 31.0' (To nail) healed
face
14"x3' Hemlock stump (to nail) healed face S.19°E.,
20.8'