

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 6 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 15 Page(s) 6203) (Duplicate Pg. 6827)

-----  
Set a porphyry stone 14x12x6 ins., 9½" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which  
A Fir 10" dia., bears N.35°W., 4 lks. dist. mkd. ¼ S31 BT  
A Madrone 6" dia., bears S.40°E., 3½ lks. dist. mkd. ¼ S6 BT.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6221-22)

-----  
Intersect the ¼ sec. cor., which is a porphyry stone, firmly set, marked and witnessed as described by the surveyor general. I change this cor. to refer to sec. 6, T30S R2W only by destroying all marks referring to sec. 31 and marking ¼ on S. face. From cor.  
A Fir 12" dia., bears S.2°15'E., 20 lks. dist., mkd. ¼ S6 BT. (New BT)  
A Madrona 6" dia., bears S.40°E., 3½ lks. dist. mkd. ¼ S6 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-32

-----  
Found - Stone at ¼ corner, approx. size, mkd. "¼" on top. 12" D.Fir now rotten stump, S.2°E., 13.2 ft., found scribing.  
6" now 8" Laurel S.40°W., (Rec. S.40°E.) 2.3 ft., rotten faces.

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S  
T 30 S R2W ¼ S 6  
1968

New BTs- 5" D.Fir S.41°E., 17.4 ft. mkd. ¼ S6 CS BT.  
30" D.Fir S.35°W., 18.9 ft. mkd. ¼ S6 CS BT.  
This corner lies 100 ft. East of 1/4 cor. Sec. 31, T29-2

Fd. and used in BLM resurvey by Peter Peterson and Daniel Berry under Group #749, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14919-20)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 6 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Randall Smith and Stephen  
Flause, crew - June 6, 1985 - C.S. File 62/28-3

-----

Found - Orig. porphyry stone measuring approx. 14x12x6" with  
possible "4" marked on S. face. This stone is  
loosely set on surface of ground at E. edge of  
brass cap monument.

An Iron pipe and brass cap monument properly mkd.,  
and firmly set, protruding 12" from ground.

Orig. BT, a 10" now 16" DBH D.Fir with X chopped in  
bark and a partially healed blaze, obliterated  
face, bears N.35°E., 2.6 ft. (Rec. N.35°W., 2.6  
ft.)

Orig. BT, a 6" Madrone now 9", DBH Madrone with a  
partially healed rotted out blaze, bears S.57°W.  
at center of root crown, and S.40°W., at center  
of trunk, blaze height, 2.3 ft. (Rec. S.40°E.,  
2.3 ft.)

A 12" dia. Fir now a severely rotted, 6" tall broken  
Fir stub with no identifiable marks bears  
S.2¼°E., 12.2 ft. to center of apparent root  
crown. (Rec. S.2¼°E., 13.2 ft.)

5" D.Fir now a 9" DBH D.Fir bears S.41°E., 17.4 ft.,  
as per record, with fully healed single blaze.

30" DBH D.Fir with a fully healed single blaze and  
a "B" chopped into the bark, bears S.35°W., 18.9  
ft. (as per record)

New BT - 6" DBH D.Fir, double blazed and scribed "¼ S6 CS BT"  
bears S.14½°E., 18.0 ft.

Fd. DCSO BC & BTs by Troy Rambo, July 2002 M140-73