

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16 & 17 only, (North)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6831)

Set a basalt stone 18x10x7 ins., 12" in the ground for cor. of secs. 16 and 17, marked with 4 notches on S. and E. edges, from which

A Cedar 9" dia., bears S.50°E., 52 lks. dist. mkd. T30S R2W S16 BT.

A Maple 18" dia., bears S.57°W., 39 lks. dist. mkd. T30S R2W S17 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Oct. 15, 1968 - C.S. File 54/73-6

Found - 18" Maple, now dead, S.57°W., 25.7 ft., found scribe "30S 2W".

Found stone at sec. cor. mkd. with renewal notches. No trace of SE. BT.

Set Brass cap at cor. mkd: County Surveyors Office

T	30	S	R	2	W
S 8					
S	17		S	16	
1968					

New BTs- 8" Cedar S.81°W., 48.6 ft. scribed T30S R2W S17 CS BT.

8" Cedar N.69°E., 23.2 ft. scribed T30S R2W S8 CS BT.

This cor. lies 115.5 ft. West of Sec. cor. for 8 & 9 only.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - 7/18/2000 - C.S. File 66/16-24

1968 John Powell found 1909 stone, set BC/IP alongside. BLM wants to monument stone position. Asked what we would like to do with our BC/IP. We cut off BC & leave in position per RWS.

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1953, surveyed June/July 2000. (DCSO rec. Vol. 53 page(s) 20676-7)

The cor. of secs. 16 & 17 only, recovered by Powell, in 1968, monumented with the original basalt stone, 18x10x7", firmly set projecting 2" from the ground, 4 notches visible on the east face, alongside of which is an iron pipe, 1½" diam., firmly set, projecting 13 " above ground, with brass cap mkd.

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 277500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16 & 17 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

COUNTY SURVEYORS OFFICE T30SR2W S8 S17 S16 1968. (The record indicates the iron post was set alongside the original stone monument and is not accepted as the cor. position and not utilized in the course of this survey.)

from which the remains of an original bearing tree

A roothole, bears S.57°W., 25.7 ft., with a badly decayed maple trunk alongside, size indeterminate, reverse scribe marks S visible.

and bearing trees mkd. by Powell

A cedar, 20" diam., bears N.67°E., 23.1 ft., with a healed double blaze.

A cedar, 16" diam., bears S.82¼°W., 48.8 ft., with a healed double blaze.

At the corner point.

Set a stainless steel post, 28" long, 2½" diam., 19" in the ground, with brass cap mkd.

T 30 S R 2 W
S 8

S 17 S 16
2000

Deposit a magnet in a white plastic case at the base of the stainless steel post. Invert and bury the original stone along the north side of the post.

At the request of the Douglas County Surveyors Office, the iron pipe is left in place and the brass cap removed.

From this point, the cor. of secs. 8 and 9 only, perpetuated by the Powell, further perpetuated by Shaner, in 1981, from original evidence no longer in existence, recorded in the Douglas County Surveyors Office, corner renewal file, T.30S., R.2W. No. 300500, & Map File No. RM3-35, bears N.89°38'37"E., 114.96 ft., monumented with an iron pipe, 1½" diam., firmly set, projecting 12" above ground, with brass cap mkd.