

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 17 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6856)

-----  
Set a basalt stone 14x8x6 ins., 9½" in the ground for ¼ sec. cor. on E. bdy. sec. 17 only, marked ¼ on W. face, from which  
A Fir 8" dia., bears S.59°W., 40 lks. dist. mkd. ¼ S17 BT.  
A Maple 10" dia., bears N.62°W., 23 lks. dist. mkd. ¼ S17 BT.

Douglas County Surveyors Office - James W. Byron, Surveyor  
John Powell and crew - C.S. File 54/73-13A - Oct. 1968

-----  
Corner searched for, not found. This corner lies 99.0 ft. North of 1/4 Cor. for Sec. 16 which falls in old landing or road. All evidence gone.

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1953, surveyed June/July 2000. (DCSO rec. Vol. 53 page(s) 20675-6)

-----  
Point for the 1/4 sec. cor. of sec. 17 only, at proportionate distance, there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd.

T 30 S R 2 W  
1/4  
S 17 |  
2000

from which  
A fir, 12" dia., bears S.50°W., 48.1 ft., mkd. ¼ S17 BT.  
A cedar, 9" dia., bears N.22½°W., 60.1 ft., mkd. ¼ S17 BT.  
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description.  
Deposit a magnet in a white plastic case at the base of the stainless steel post.