

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6766)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 6" dia., bears N.30°E., 12 lks. A Fir 18" dia., bears S.22°E., 28 lks.</p>
<p>GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6799 and 6811)</p> <p>-----</p> <p>(Page 6799) The ¼ sec. cor. partially obliterated. No trace is found of the post and the bearing trees are deeply overgrown. (Page 6811) I re-establish the ¼ sec. cor. in its original position as follows: Set a basalt stone 16x10x6 ins., 11" in the ground, for ¼ sec. cor. mkd. ¼ on N. face, from which A Fir 10" dia., bears N.67°W., 12 lks., mkd. ¼ S15 BT. A Fir 30" dia., bears S.36°E., 30 lks., mkd. ¼ S22 BT.</p>
<p>BLM resurvey by C. Albert White, Cadastral Surveyor, under Group #524, surveyed Aug/Sept. 1963 - (DCSO records Vol. 32 Page(s) 13419)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 15 and 22, restored by the method of irregular boundaries, based on Mensch's resurvey; there is no remaining evidence of the original corner. Set an iron post 28" long, 1½" dia., 22" in the ground, with brass cap mkd: ¼ $\frac{S\ 15}{S\ 22}$ T 30 S R 2 W 1963</p> <p>from which A conglomerate boulder, 29x15x9 ft. above ground, bears N.32½°W., 71 lks. dist., mkd. B X O. A conglomerate boulder, 16x15x14 ft. above ground, bears S.36 ¾°E., 53 lks. dist., mkd. B X O.</p>
<p>Fd. OK, Oct. 1996 by K. DeGroot - M 125-80</p>
<p>BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22653-4)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 15 & 22, monumented with an iron post, 2½" dia., firmly set, projecting 2" above a collar of stone, with brass cap (properly) mkd. continued next page</p>

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which a bearing object mkd. by White in 1963
A conglomerate boulder, 16x15x14 ft., bears S.36 $\frac{3}{4}$ °E., 35.0
ft., mkd. B X O.
and a new bearing tree
A fir, 10" dia., bears N.7 $\frac{1}{2}$ °E., 9.0 ft., mkd. $\frac{1}{4}$ S15 BT.
Corner is located on a SE. slope, in the area affected by the
1962 landslide reported by White.
NAD 1983 (COR)
Latitude: 42°57'37.90"N Longitude: 122°55'57.40"W