

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 12 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6802)</p> <p>-----</p> <p>Set a porphyry stone 12x8x6 ins., 8" in the ground for ¼ sec. cor. on S. bdy. sec. 12, marked ¼ on N. face, from which</p> <p>A Fir 18" dia., bears N.40°E., 9 lks. dist. mkd. ¼ S12 BT.</p> <p>A Fir 18" dia., bears N.70½°W., 46 lks. dist. mkd. ¼ S12 BT.</p>
<p>Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - March 24, 1960 - C.S. File 42/421-15</p> <p>-----</p> <p>Determined by O.B.T.:</p> <p>20" Fir, uproot, N.40°E., 5.9 ft., found scribe.</p> <p>At corner point, SET 1/2" x 30" Iron pipe, from which</p> <p>9" Cedar S.21°W., 36.5 ft. mkd. ¼ S12 BT.</p> <p>28" Cedar N.47°W., 41.0 ft. mkd. ¼ S12 BT.</p> <p>North ¼ corner 13 bears West 58.0 ft. distance.</p>
<p>Dennis Gaylord, U.S. Forest Service (Deputized by the County) Wit: James Davis - Aug. 30, 1978 - C.S. File 60/11-33</p> <p>-----</p> <p>Found - 1" x 34" Iron pipe set solidly in ground.</p> <p>Orig. BT to the NE. is blown down, stump hole bears N.40°E., 5.9 ft.</p> <p>A 14" Cedar bears S.21°W., 36.1 ft., scribing visible "BT ¼ S12" on a single blaze.</p> <p>A 20" Cedar bears N.47°W., 40.4 ft. scribed "¼ S12 BT" on a double blaze.</p> <p>Brass cap for S13 only, which (I renewed this AM) bears N.89°45'W., 57.5 ft.</p> <p>Referencing the Iron pipe, I move it aside and SET in its place a 1½" I.P. with a 2½" brass cap stamped "County Surveyors Office T30S R2W ¼ S12 1978". I bury the 1" Iron pipe alongside the brass cap.</p> <p>No new accessories.</p> <p>I placed County BT signs on both BTs.</p> <p>Local attraction caused by a metal fence post setting 1.2 ft. East of the brass cap.</p>
<p>Fd. & used on BLM dependent resurvey by Wayne Rogers, Cadastral Surveyor and Robert Browning, under Group #1883 surveyed June/July 1998 - (DCSO recs. Vol. 53 Pg(s) 20345-6)</p>
<p>Found OK by B. Shaner, Mar. 2001 - M132-75 & CS65/36-12F</p>
<p>continued next page</p>

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 12 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

David Edwards - Crew: Brant Miller & Eric Sprinkle -
2/20/2017 - C.S. File 65/95-27

Found - Standard 1978 DCS brass capped iron pipe in good condition.

Bearing trees by Markham:

20" dia. Cedar with healed blaze bears S.20 $\frac{3}{4}$ °W., 36.3'

25" dia. high Cedar stump with healed blaze bears

N.46°W., 40.9'

No other previous accessories remain.

New - An 8" diam. Fir scribed "1/4 S12 BT" bears N.66°W.,
16.5 ft.

A six foot steel post is set 2 feet North.

Compass Declination 15° East