

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION C C for Secs. 7 & 18 only, West Bdy.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

by Thompson in 1956, monumented with an iron pipe, 1" dia., firmly set, extending 3" above ground, from which the original bearing trees:

A sawed Fir stump 38" dia., bears N.23 3/4°E., 14 lks. dist. mkd. T30S R3 S on opened blaze.

A Fir snag 22" dia., bears S.43½°E., 17 lks. dist. with opened and burned blaze.

A rotted Fir stump 14" dia., bears N.53°W., 45 3/4 lks. dist. mkd. 30 R3W 7 on section of blaze lying beside stump. (Rec. N.51°W.)

and bearing trees marked by Thompson

A Cedar 12" dia., bears N.56½°E., 66 lks. dist. mkd. T30S R3W S7 BT on partly healed double blaze.

A Fir 19" dia., bears N.41°W., 121 lks. dist. mkd. 30 R3W BT on partly healed double blaze.

From this same point, the angle point bet. secs. 12 and 18 bears S.2°17'W., 8.85 chs.

David Edwards - For: Swanson Group, INC - 4/2007 - M152-75

Found - BC

1965 BLM BTs fall in road area & are gone.

14" Cedar by Thompson bears N.0°24'E., 21.1', with healed blaze.

Fir stump bears N.57°W., 105.5'

Set - 6' steel post N.2°E., 2 ft.