

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6973)

Set a stone 14 x 12 x 4 ins., 10" in the ground, for 1/4 sec. cor. marked 1/4 on N. face, from which

A Fir 7" dia., bears N.36 1/2°E., 14 lks. dist. mkd. 1/4 S BT.

A Fir 30" dia., bears S.75°E., 35 lks. dist. mkd. 1/4 S BT.

Survey by Robert M. Thompson - Feb. 11, 1956; April 1, 1956 -C.S. File 42/173

Found stone and 2 BTs, scribing visible.

Marked new tree:

12" D.Fir N.41°30'W., 24.1 ft.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #599, surveyed Sept. 1965 - (DCSO records Vol. 33 Page(s) 13906-07)

The 1/4 sec. cor., perpetuated and recorded by Thompson in 1956, monumented with an iron pipe, 1" dia., firmly set, extending 3" above ground, with original basalt stone 14 x 12 x 4 ins., lying on the ground, marked 1/4, from which the original bearing trees:

A Fir snag 9" dia., bears N.36 1/2°E., 14 lks. dist. mkd. BT on opened blaze.

A Fir 46" dia., bears S.75°E., 33 lks. dist. with healed blaze. (Rec. 35 lks.)

and a bearing tree mkd. by Thompson:

A Fir 15" dia., bears N.41 1/2°W., 37 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

T 30 S R 3 W

1/4 S 7

S 18

1965

Deposit the original stone and the iron pipe alongside the iron post.

From this point, a United States Geological Survey Bench mark, bears S.49°32'W., 41.53 chs. dist., monumented with a brass cap 3 1/2" dia., firmly seated in the top of a boulder 8" above ground, mkd. BLAND MTN. 1953. The bench mark is under Bland Mountain Lookout Tower.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyor Office - Larry E. Monrean; G.E. Quibell;
D.L. Stewart - March 5, 1981 - C.S. File 64/1-15

REFERENCED NOTES ONLY

Found - Orig. 8 x 11 x 4 stone (Rec. 14x12x4) marked "¼ on top of ground along northerly side of iron pipe and brass cap monument, a 1965 GLO brass cap, mkd. "¼ S7 S18 1965"
1" I.P. along northerly edge of I.P. monument.
Orig. 7" now 8" Fir snag, scribed "¼ S" on previously opened blaze, bears N.41½°E., 9.9 ft. (Rec. N.36½°E., 9.2 ft.)
Orig. 30" now a 46" Fir, with well healed blaze, bears S.75°E., 22.2 ft. (Rec. 23.1 ft.)
A Fir 12" now 14", bears N.38½°W., 23.8 ft. (Rec. N.41½°W., Ok at top of blaze.) Blaze is well healed.

This area soon to be logged. We reference as follows:
We reference position of BLM brass cap and dig up cap. Set 1" x 18" I.P. from 1956 Thompson visit, 12" below surface directly over I.R. Set original stone along North edge of I.P., 12" below surface. Reset BLM brass cap at referenced position with cap 2" above surface. Set 4 PK nails in notched roots as follows:

- A 48" Fir, PK bears S.71½°W., 49.2 ft. (Tree has large opening in East face)
- 14" Fir, found BT, PK bears N.40°W., 22.5 ft.
- 24" Fir, PK bears N.22½°E., 40.1 ft.
- 46" Fir, found BT, PK bears S.76°(?) 19.8 ft.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Aug. 9, 1989 - C.S. File 64/1-15

Found - 1965 3¼" dia. BLM brass cap on a 2" dia. Iron ipe, protruding 2" above ground.
5/8" Iron rod, 1" Iron pipe and orig. stone set below ground in 1981, not looked for.
7" now 8" dia. D.Fir snag with a previously opened blaze, scribing visible "¼S", bears N.41½°E., 9.9 ft. (agrees with 1981 record) Orig. BT.
30" now 46" dia., 5 ft. high D.Fir stump with fully healed double blaze, bears S.75°E., 22.2 ft. (agrees with 1981 record) PK nail set at West base, bears S.76°E., 19.3 ft. (Rec. S.76°E., 19.8 ft. per 1981) Orig. BT.
12" now 15" dia., D.Fir with fully healed double

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

blaze bears N.38½°W., 22.6 ft. (Rec. N.38½°W., 23.8ft. in 1981) PK nail set at SE base bears N.40°W., 22.5 ft. (agrees with 1981) BT from 1956)

24" now 30" dia., 3 ft. high D.Fir stump with PK nail at SE base, PK bears N.22½°E., 40.1 ft. (agrees with 1981 visit)

48" ow 49" dia. D.Fir with large opening on East trunk, PK nail set at SE base, PK bears S.71½°W., 49.2 ft. (agrees with 1981 record)

New BTs- 30" dia., 2½ ft. high D.Fir stump with boat spike driven in top near center of stump, stamped "BO 1" BS, bears N.19¼°E., 40.4 ft. (A PK nail reference tree from 1981)

4" dia. Madrone with previous bark scribing "KB SS", we double blaze and scribe "X BT", bears S.67 3/4°W., 5.4 ft.

Corner lies on a steep West slope approx. 75 ft. West of a N-S ridge top road at the South edge of a recent clear cut.