

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 037060

PRIMARY CORNER DESCRIPTION SE Cor. Jacob Slippery DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey) (Pg. 595 DLC Volume)

-----  
Set a post marked, from which  
A B.Oak 9" dia., bears N.50°W., 28 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (Page 691 DLC Volume)

-----  
The post set for this cor. is gone, but the bearing tree is standing. I restore this corner by setting an Oak post, 4½ ft. long, 4" sq., 24" in the ground marked T30S R4W C. 37 on NW. face, from which  
A B.Oak 15" dia., bears N.50°W., 28 lks. dist. mkd. T30S R4W C. 37 BT.

John H. Markham, Jr. - Wit: B.E. Blomgren - For: Stomar Lumber Co. - June 1953 - C.S. File 41/161-4

-----  
Determined by O.B.T.  
A 14" B.Oak snag bears N.50°W., 18.5 ft., found scribe.  
At corner point, Set 1" x 20" Iron pipe, from which  
An 18" B.Oak bears N.54°W., 60.0 ft. mkd. Cl. 37 BT.  
A 12" laurel bears West 36.0 ft. mkd. Cl. 37 T30S R4W BT.  
Fences run N. and W. from corner.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - July 1963 - C.S. File 53/26

-----  
Found - Iron pipe at corner.  
NW BT burned. West BT dead.  
New BTs - 12" Laurel S.78°E., 51.5 ft. scribed SE DLC 37 CS BT  
12" Laurel S.25°W., 52.0 ft. scribed SE DLC 37 CS BT

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 3/27/2017 (Filed 11/10/2021) - C.S. File 67/49-19

-----  
Found - 1" I.D. iron pipe protruding 6" above ground and leaning 0.5 ft. NW off of plumb. Markham described mon. as a 1"x20" iron pipe, we find it to measure 16" long. 1953  
Possible evidence of OBT: 9" B.Oak now a distinct large root hole, the deeper part of which bears N.50°W., 18.5 ft. (as per record)  
A 12" laurel, now the rotted and burned remains of a Madrone root crown with 5 sprouted living Madrone trunks on it's easterly edge. The center of fd root crown bears West 36.0 ft. (as per rec) 1953 cont.

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 037060

PRIMARY CORNER DESCRIPTION SE Cor. Jacob Slippy DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An B.Oak, now a large but indistinct root hole is fd near record B and D. 1953  
Byron's 1963 SE BT gone; old skid-road through location.  
A 12" Laurel now a 26" dia., Madrone stump with a F.H.D.B.; bears S.24°W., 48.8 ft. (rec. S.25°W., 52.0 ft. a reasonable slope distance) 1963  
New - Plumb position of fd 1" iron pipe is accepted. Position is referenced out and iron pipe is removed. At the referenced position is set a 2 3/8" dia. Brass cap on a 1" ID x 32" iron pipe protruding 7" above ground. The fd 1x16" iron pipe is set on south edge of BC/IP monument and protrudes 4" above ground, BC marked:  
DOUGLAS COUNTY SURVEYOR  
T30S  
SE |  
DLC 37 |  
R4W  
2017  
A 10" dia. D.Fir scribed "SE DLC 37CS" "BT" on a double blaze; bears N.31°E., 18.9 ft.  
An 8" dia. D.Fir scribed "SE DLC 37CS" "BT" on a double blaze; bears S.72°E., 14.7 ft.  
A 14" dia., Madrone (Most southerly of 5 Madrone root crown sprouts previously noted in fd 1953 BTs) scribed "SE DLC 37" "CSBT" on a double blz. The center of the root crown of the scribed trunks parent tree bears West 36.0 ft. (as previously noted) The center of the base of the scribed trunk itself bears S.86¼°W., 34.3 ft.  
A 6" dia., D.Fir scribed "X" "CSBT" on a High-Low blz. Bears N.76¼°W., 48.1 ft.  
The SW corner of DLC 40 (A DCSO brass cap monument) bears N.1°22'W., 657.07 ft (Original and 1892 GLO resurvey, North 660 ft.; Markham 1953 renewal of SW DLC 40, North 669 ft)