

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 039080

PRIMARY CORNER DESCRIPTION WC Pt on SE Bdy Beckworth DLC #39

Alias 042030 Description Int. L Kemuel DLC #42  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey) (Pg. 598 and 603 DLC Volume)  
-----  
(Page 598) Set a post marked from which  
A Maple, 4" dia., bears N.45°W., 31 lks.  
(Page 603) Set a post from which  
A Maple, 4" dia., bears S.45°E., 16 lks.(gone)  
A Maple, 16" dia., bears S.62°E., 35 lks. (Last Witness tree added by County Surveyor in 1913)

Resurvey - Wm. Thiel, under Contract dated Feb. 5, 1889 (DLC Volume, page 695 & 701)  
-----  
10.00 chs - Corners comes in the river.  
10.62 chs - Left bank of river: corn. & BTs are washed away; set as witness corner 62 lks. E of true corner a basalt stone 10x8x8", 7" in ground, marked 39 WC on NW face, (page 701, 42 WC on SE face) and raised a mound of stone along side.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCS0 records Vol. 52 Page(s) 20135-6)  
-----  
True point for the interior L cor. of DLC 42, at proportionate dist., determined by the Grant Boundary Method between the reestablished SW. cor. of DLC 42 and the reestablished NE. cor. of DLC 42, there is no remaining evidence of the original corner, not monumented, point falls in the South Umpqua River.  
From this point, the point selected for the witness cor. to the interior L cor. of DLC 42, bears S.0°19'41"E., 0.900 chs. Set a stainless steel post, 28" long, 2½" diam., 27" in the ground, with brass cap mkd.  
W C  
T30S R4W  
S 8 | C42  
1994  
from which  
A maple, 11" diam., bears S.85½°E., 35½ lks., mkd. X BT.  
An ash, 19" diam., bears N.26¼°W., 12 lks., mkd. X BT.  
Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.  
The corner is located N., 0.80 chs. of the center of County Road No. 1 (Tiller Trail Highway), asphalt-surfaced, 40 lks. wide, bears N.65°E. and S.70°W.

continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 039080

PRIMARY CORNER DESCRIPTION WC Pt on SE Bdy Beckworth DLC #39

Alias 042030 Description Int. L Kemuel DLC #42  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 3/2/2017 (filed 11/10/2021) - C.S. File 67/49-18

- 
- Found - 1994 BLM 3¼" brass cap on a 2" I.D. IP sitting plumb and having top flush with ground. (Brass cap properly marked)  
No evidence of the 1889 stone monument, once set to the NE is found.  
A maple 11" dia., now a 15" Maple with a fully healed high-low blaze, bears S.85½°E., 23.4 ft. (as per record.) 1994  
An Ash 9" dia., now a tipped out buried tree with possible root-wad mound evidence near record B and D. 1994
- New - A 15" dia., Maple, scribed "WC Int L DLC 42" "CSBT" on a double braze; bears N.45°E., 26.1 ft.  
A federal highway administration survey control point, identified in D.C.P.W. records as "PΔ315" is a 1/2" dia., iron rod with a 1" dia., yellow plastic cap marked "FHWA/CP" bears S.34°06'36"W., 119.6 ft. (bearing is determined from tying into D.C.P.W. survey) this IR/plstc cap is buried 6" deep in south road shoulder and is 18 ft. from Co. Rd. #1's centerline.
- Note - BT meas. Are compass brng's Dec. 15°E.