

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 046010

PRIMARY CORNER DESCRIPTION NE Cor. Alexander Dumond DLC #46

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - GLO survey by J.A. Burnett, under Contract dated Sept. 1855 (DLC survey) (DLC Vol. Page 609)

Set a post, from which
A B.Oak 8" dia., bears S.15°W., 15 lks.
A B.Oak 15" dia., bears S.15°E., 14 lks.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records DLC Volume Page 709)

The NE. Corner, a Post without marks is in place, probably set by the Co. Surveyor; the bearing tree SE. of cor. is standing; and a stump of a B.Oak, corresponding in size, direction and bearing with the field notes of original survey. I replace the partially decayed post and restore the corner by setting a Laurel post 4½ ft. long, 4" sq., 24" in the ground, marked T30S R4W C. 46 on the SW. face, from which
A B.Oak 24" dia., bears S.15°E., 14 lks. dist. mkd. T30S R4W C. 46 BT. This is the old bearing tree, whose marks being dim, I renew.
A Laurel 6" dia., bears S.47°W., 23 lks. dist. mkd. T30S R4W C. 46 BT.

G.G. Stewart - Wit: H.A. Hill - April 6, 1922 - C.S. File 7/6

Set Iron pipe from orig. BT.
A 24" B.Oak S.15°E., 9.2 ft. (orig. BT)
A 20" B.Oak N.7°E., 44.0 ft.

Fd. I.P. and BTs OK, June 1970 by L. Bishop - M 42-1

Douglas Co. Surveyors Office - Crew: Stephen Flause & Mike Koch - 6/20/2017 (filed 11/8/2022) - C.S. File 67/54-55

Found - 1925 DCSO Iron Pipe, now a 1/2" I.D. iron pipe, 27" long, tipped and bent SSE, protruding approx. 3" above ground. (Length determined when monument was removed from ground to straighten)
Measurements are from plumb position of fd IP monument.
A B.Oak, 15" dia., now a 35" dia., broken topped but still alive B.Oak snag with a fully healed double blaze; bears S.15°E., 10.8 ft. (rec. S.15°E., 9.2 ft would be good to orig. face) 1855 OBT
B.Oak 8" dia., is now a shallow root depression near the original bearing and distance. 1855 OBT
A Laurel 6" dia., now a distinct roothole S.47°W., 115.2 ft. (as per record) 1889

continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 046010

PRIMARY CORNER DESCRIPTION NE Cor. Alexander Dumond DLC #46

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 20" B.Oak, now a fallen rotted and out of position
22" dia., B.Oak. Tree is fallen on face (Blaze
evidence not seen) The root crown of this tree is
still intact and in position and bears N.7°E.,
42.6 ft. (Bearing is as per record, record
distance of 44.0 would be a good slope
measurement) 1922

New - Plumb position of found IP is referenced out. Pipe
is removed from ground, straightened and returned
to the referenced position.

A double trunk Madrone scribed "NE DLC 46 CS" "BT"
on a double blaze on its 30" dia., southerly
trunk. The center of the root crown of the double
trunk bears N.26°E., 9.8 ft.

A 14" dia., I.Cedar scribed "NE DLC 46 CS" "BT"
on a double blaze, bears S.84½°W., 17.0 ft.

A 7" dia., D.Fir scribed "X" "CSBT" on a high-low
blaze; bears N.21°W., 3.1 ft.

Note - Compass decl. 15°E.