

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 050040

PRIMARY CORNER DESCRIPTION SE Cor. Joseph P. Wilson DLC #50

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey Volume, Page 616)

Summit of mountain. Set a post marked, from which
A B.Oak 8" dia., bears N.73°W., 20 lks.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records DLC Volume Page 721)

The post set for this corner is gone, but the bearing tree, marked T30S R4W C.50 BT an Oak 9" in dia. is standing, but killed by fire. I restore this cor. by setting a sandstone 12 x 8 x 6 ins., 8" in the ground, marked 50 on NW. face, from which
A Fir 10" dia., bears N.80°W., 5 lks. mkd. T30S R4W C50 BT
A Laurel 6" dia. bears N.15°E., 16 lks mkd T30S R4W C50 BT

F.C. Frear, Deputy Co. Surveyor - Wit: A. Wallenburg; R. Morrison - Oct/Nov. 1918 - M 1-3; Vol. 3 Pg. 29; C.S. File 7/18 and Field book 14=45

Renew from government BTs. Set in 1½" x 30" galv. Iron pipe and 4" x 48" Fir stake, from which
A 10" Fir bears S.56°E., 7 lks.
A 10" Fir bears N.88¼°W., 11½ lks.

Douglas Co. Surveyors Office - G. Langlitz; G. Quibell; A. Cangie; Debbie L. Stewart, crew - April 21, 1976 - C.S. File 59/8-20

Found - 1½" I.P. and probable remains of a 4" stake set by Frear in 1918.
No trace of original bearing tree.
A windblown Fir 12" bears S.56°E., 4.6 ft. We open to find visible scribe "CS 50 BT".
The probable remains of a NW. BT also down, 10". Its root wad bears N.88¼°W., 7.6 ft. We do not unearth, blaze is buried face down, and we do not open.

Set a 1"x30" I.P. with brass cap stamped:
County Surveyors Office
T 30 S R 4 W
S.E. | D.L.C.
Cor. | 50

1976

with the found 1½" I.P. on the West side of brass cap.
(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 050040

PRIMARY CORNER DESCRIPTION SE Cor. Joseph Wilson DLC #50

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs -12" D. Fir bears N.3½°W., 44.8 ft. scribed "SE DLC 50 CS BT" in double blaze.
6" Madrone bears N.62°W., 3.5 ft. scribed "SE DLC 50 CS BT" in double blaze.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/13/2018 (Filed 11/8/2022) - C.S. File 67/54-56

Found - 1976 2½" brass cap on a 1" iron pipe projecting 2" (properly mkd)
1½" IP on west side of brass cap projecting 1" 18" dia. Fir stump 10" tall bears N.3½°W., 44.8 ft. with a fully healed lower blaze. 1976
11" dia. Madrone bears N.62°W., 3.5 ft. with a fully healed double blaze. 1976
New - 13" dia. Madrone scribed "SE DLC 50", "CS BT" on a double blaze bears S.46°E., 13.5 ft.
17" dia. Fir scribed "SE DLC 50", "CSBT" on a double blaze bears S.61¼°W., 16.2 FT.

Note - Location & comments: the iron rod monument with cap is located near the top of East-West ridge Westerly of Gilbeaugh Creek Road (BLM 70) in a reprod forest of Madrone and Fir. A 2" wide galv. U-Post projecting 4 ft above ground bears S.80½°W., 1.85 ft from the monument. (Best access is from BLM Rd. 70 following the ridge line down from the y intersection)
Declination 15°E.